

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5328L - EQ

ROEL

Not Authorised

1-B.1

8890.00

Resurvey B4 point

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5328L - ROEL
 VF1ABL15AUC276880
 RENAULT
 LATITUDE
 04.06.2015
EQ

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>See</i> 968.78 X
2	1	HEADLAMP RH	\$	<i>See</i> 911.10 X
3	1	FENDER PANEL FRT RH	\$	<i>See</i> 602.95 X
4	1	DOOR PANEL FRT RH	\$	<i>See</i> 2,188.20 X
5	1	DOOR MIRROR RH	\$	<i>See</i> 1,141.08 X
6	1	DOOR MOULDING FRT RH	\$	<i>See</i> 136.01 X
7	1	DOOR SEAL FRT RH	\$	<i>See</i> 56.02 X
8	1	DOOR HANDLE OUTER FRT RH	\$	<i>See</i> 198.55 X
9	1	DOOR HANDLE CAP FRT RH	\$	<i>See</i> 20.34 X
10	1	DOOR HANDLE SEAL FRT RH	\$	<i>See</i> 6.07 X
11	1	ROCKER PANEL OUTER RH	\$	<i>See</i> 759.61 X
12	1	DOOR PANEL REAR RH	\$	<i>See</i> 2,188.20 X
13	1	DOOR HANDLE OUTER RR RH	\$	<i>See</i> 198.55 X
14	1	DOOR MOULDING RR RH	\$	<i>See</i> 137.21 X
TOTAL			\$	9,512.68
10%			\$	951.27
			\$	8,561.41

Special Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>See</i> 66.00 X
2	1SET	WHEELARCH CLIP RH	\$	<i>See</i> 66.00 X
3	1SET	REAR BUMPER CLIP	\$	<i>See</i> 66.00 X
4	1	CAP HUB RH FRT	\$	<i>See</i> 35.00 X
5	1	RIM RH FRT	\$	<i>See</i> 385.00 X
6	1	TYRE RH FRT	\$	<i>See</i> 330.00 X
7	1	DOOR STICKER "Trans-cab"RH	\$	<i>See</i> 80.00 60SN
8	1	DOOR STICKER "Classic"RH	\$	<i>See</i> 30.00 15SN
9	1	DOOR STICKER "6555-3333"	\$	<i>See</i> 80.00 60SN
TOTAL			\$	1,138.00
TOTAL PARTS			\$	9,699.41

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5328L - EQ**ROEL**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	1,400.00	3001
To Check Electrical Lighting Concerned.	\$	170.00	151
Putty and spray painting of the affected portion.	\$	1,500.00	4401
To check steering geometry and computer wheel alignment	\$	220.00	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ 170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	~ 170.00 X
To rust-proofing of the affected areas.	\$	170.00	~ 170.00 X

TOTAL \$ 3,800.00**Over All Total** \$ 13,499.41**(PARTS BY PARTS) Repair Days****10 Days**

1 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: