

ARC**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2007-087
DATE : 8-Jul-2020
POLICY NO. : P10364375R00
VEHICLE REG. NO. : SLB7467M
VEHICLE MAKE : MITSUBISHI LANCER EX 1.6 ATTO Motor Claim Department
First Capital Insurance Limited
36 Robinson Road #16-01 City House
Singapore 068877
Tel: 6507 3848, Fax: 65073849

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Bumper / CRU.	1	\$ 880.00	\$ 880.00
2	Front Bumper Clips / NEC	10	\$ 5.00	\$ 50.00
3	Front Bumper Towing Cap / CRU.	1	\$ 40.00	\$ 40.00
4	Front Bumper Top Beam XSV	1	\$ 80.00	\$ 80.00
5	Front Bumper Lower Grille / CRU	1	\$ 90.00	\$ 90.00
6	Front Bumper Lower Grille Chrome Moulding / CRA	1	\$ 250.00	\$ 250.00
7	Front Bumper Lower Grille Cap RH XSV	1	\$ 10.00	\$ 10.00
8	Front Bumper Lower Grille Cap LH XSV	1	\$ 10.00	\$ 10.00
9	Front Reinforcement / BT	1	\$ 380.00	\$ 380.00
10	Front Bumper Retainer RH / BR	1	\$ 20.00	\$ 20.00
11	Front Bumper Retainer LH / BR	1	\$ 20.00	\$ 20.00
12	Front Bumper Grille Assy / CRA	1	\$ 280.00	\$ 280.00
13	Front Bumper White Bracket RH / CRA	1	\$ 20.00	\$ 20.00
14	Front Bumper White Bracket LH / CRA	1	\$ 20.00	\$ 20.00
15	Front Bumper Undercover / cut	1	\$ 180.00	\$ 180.00
16	Front Bumper Undercover Clip / NEC	10	\$ 5.00	\$ 50.00
17	Front Emblem / NEC	1	\$ 60.00	\$ 60.00
18	Head Lamp RH / CRU	1	\$ 780.00	\$ 780.00
19	Head Lamp LH / CRA	1	\$ 780.00	\$ 780.00
20	Head Lamp Bracket RH XSV	1	\$ 70.00	\$ 70.00
21	Head Lamp Bracket LH XSV	1	\$ 70.00	\$ 70.00
22	Front Support Panel Top Garnish Cover / / CRU.	1	\$ 70.00	\$ 70.00
23	Front Support Panel / pb	1	\$ 400.00	\$ 400.00
24	Front Brace Panel / BT	1	\$ 220.00	\$ 220.00
25	Radiator / pb	1	\$ 1,180.00	\$ 1,180.00
26	Radiator Tank XSV	1	\$ 60.00	\$ 60.00
27	Radiator Fan Blade ?	1	\$ 70.00	\$ 70.00
28	Radiator Fan Motor ?	1	\$ 380.00	\$ 380.00
29	Radiator Fan Shroud ?	1	\$ 250.00	\$ 250.00
30	Radiator Top Bracket ?	1	\$ 20.00	\$ 20.00
31	Radiator Lower Bracket ?	1	\$ 20.00	\$ 20.00

photo

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2007-087

DATE :

POLICY NO. :

VEHICLE REG. NO. :

VEHICLE MAKE :

FOR SURVEYOR

Auto Consultants hence notify

the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TO Motor Claim Department

First Capital Insurance Limited

36 Robinson Road #16-01 City House

Singapore 068877

Tel: 6507 3848, Fax: 65073849

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
32	Radiator Upper Hose RH / <i>dep</i>	1	\$ 20.00	\$ 20.00
33	Radiator Upper Hose LH / <i>dep</i>	1	\$ 50.00	\$ 50.00
34	Radiator Cap Assy - 10210A <i>X SVC.</i>	1	\$ 80.00	\$ 80.00
35	Radiator Lower Hose <i>?</i>	1	\$ 70.00	\$ 70.00
36	A/C Condenser <i>X / CRU</i>	1	\$ 900.00	\$ 900.00
37	A/C Compressor <i>X SVC</i>	1	\$ 1,580.00	\$ 1,580.00
38	A/C Compressor Suction Hose <i>?</i>	1	\$ 300.00	\$ 300.00
39	A/C Compressor Discharge Hose <i>?</i>	1	\$ 220.00	\$ 220.00
40	A/C Pipe Inlet Hose <i>?</i>	1	\$ 180.00	\$ 180.00
41	Air Intake Duct <i>X SVC</i>	1	\$ 150.00	\$ 150.00
42	Engine Intake Manifold <i>X SVC.</i>	1	\$ 780.00	\$ 780.00
43	Engine Top Cover / <i>CRU</i>	1	\$ 150.00	\$ 150.00
44	Front Bonnet / <i>PD</i>	1	\$ 700.00	\$ 700.00
45	Front Bonnet Lock / <i>Jun</i>	1	\$ 60.00	\$ 60.00
46	Front Bonnet Hinge RH / <i>BT</i>	1	\$ 60.00	\$ 60.00
47	Front Bonnet Hinge LH / <i>BT</i>	1	\$ 60.00	\$ 60.00
48	Front Bonnet Insulator / <i>CRU</i>	1	\$ 120.00	\$ 120.00
49	Front Bonnet Insulator Clips / <i>Nec</i>	10	\$ 5.00	\$ 50.00
50	Front Bonnet Nozzle <i>X SVC.</i>	2	\$ 20.00	\$ 40.00
51	Front Bonnet Front Rubber Seal / <i>CUH.</i>	1	\$ 30.00	\$ 30.00
52	Front Bonnet Front Rubber Seal RH <i>X SVC</i>	1	\$ 30.00	\$ 30.00
53	Front Bonnet Front Rubber Seal LH <i>X SVC</i>	1	\$ 30.00	\$ 30.00
54	Front Bonnet Inner Rubber Seal / <i>Nec</i>	1	\$ 30.00	\$ 30.00
55	Front Fog Lamp RH / <i>BT</i>	1	\$ 300.00	\$ 300.00
56	Front Fog Lamp LH <i>X SVC.</i>	1	\$ 300.00	\$ 300.00
57	Front Fog Lamp LED Side RH <i>X SVC</i>	1	\$ 580.00	\$ 580.00
58	Front Fog Lamp LED Side LH <i>X SVC</i>	1	\$ 580.00	\$ 580.00
59	Front Fog Garnish RH / <i>CRA</i>	1	\$ 50.00	\$ 50.00
60	Front Fog Garnish LH <i>X SVC</i>	1	\$ 50.00	\$ 50.00
61	Front Fender RH / <i>PD</i>	1	\$ 500.00	\$ 500.00
62	Front Fender LH / <i>PD</i>	1	\$ 500.00	\$ 500.00
63	Front Fender Side Chrome RH / <i>Nec</i>	1	\$ 60.00	\$ 60.00

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2007-087
DATE : 8-Jul-2020
POLICY NO. : P10364375R00
VEHICLE REG. NO. : SLB7467M
VEHICLE MAKE : MITSUBISHI LANCER EX 1.6 AT

TO Motor Claim Department
First Capital Insurance Limited
36 Robinson Road #16-01 City House
Singapore 068877
Tel: 6507 3848, Fax: 65073849

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
64	Front Fender Side Chrome LH / Nec	1	\$ 60.00	\$ 60.00
65	Front Fender Shield RH Xsvc.	1	\$ 120.00	\$ 120.00
66	Front Fender Shield LH Xsvc	1	\$ 120.00	\$ 120.00
67	Front Fender Clip Xsvc	20	\$ 5.00	\$ 100.00
68	Front Air Bag RH @ Steering Wheel / BR.	1	\$ 1,200.00	\$ 1,200.00
69	Front Air Bag LH / BR	1	\$ 1,980.00	\$ 1,980.00
70	Front Dashboard / BR.	1	\$ 980.00	\$ 980.00
71	Front Seat Belt RH / Jam	1	\$ 700.00	\$ 700.00
72	Front Seat Belt LH / Jam	1	\$ 700.00	\$ 700.00
73	Reel Cable For Air Bag At Steering Wheel ?	1	\$ 300.00	\$ 300.00
74	SRS Control Unit / Short	1	\$ 880.00	\$ 900.00
75	SRS Sensor @ Front Bumper RH / CR4	1	\$ 250.00	\$ 250.00
76	SRS Sensor @ Front Bumper LH / CR4	1	\$ 250.00	\$ 250.00
Total Spare Parts				\$ 23,080.00
SPECIAL NETT				
77	Front License Plate with Casing / PD	1	\$ 40.00	\$ 40.00
78	Coolant Fluid 4 Litre / Nec	1	\$ 30.00	\$ 30.00
Total Special Nett				\$ 70.00
LABOUR				
79	Spray Painting Whole Front Include Front Doors	1	\$ 1,000.00	\$ 1,000.00
80	Replace Bulkhead (Include Frt Support Panel) & Affected Area	1	\$ 1,200.00	\$ 1,200.00
81	Remove and Refit Dashboard and Related Parts (Airbags)	1	\$ 300.00	\$ 300.00
82	Remove, Refit A/C Condenser, Radiator & Refill A/C Gas	1	\$ 100.00	\$ 100.00
83	Reset ECU, ABS and SRS	1	\$ 150.00	\$ 150.00
84	Computerized Wheel Alignment	1	\$ 70.00	\$ 70.00
85	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,850.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Amount Before Excess \$ 26,000.00
Add GST @ 7% 1,820.00
Total Amount Payable \$ 27,820.00

Repair days - 7 days 10 days

L/S.
After paint photo.
Sun Pin (LH/LR)
04/07/2020
TP without prejudice