

SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #13-207 Singapore 380063

Accident Car Inspection Report

Caspar Wong Ren Hao

Blk 427, Tampiness Street 42

#06-451 Singapore 520427

General Information			
Accident Date	05/11/2019	Type Survey	3 rd Party Survey
Our Reference	TP/02 /02/2020	Report Date	20/02/2020
Vehicle Details			
Vehicle No	SLF5544R	Registration Date	30/08/2016
Chassis No	WVVZZZ6RZGU027633	Odometer	7087 km
Engine No	CJZ766718	Make	Volkswagen
Engine Capacity	1197 cc	Model	Polo GP 1.2
Transmission Type	Auto	Colour	Silver
Tyres Condition			
Front: 5mm 195/65 R15 Rear: 5mm 195/65 R15			
Repairer Name			
Mun Jin Motor Services 2 kaki Bukit Avenue 2 #02-28 Kaki Bukit Autohub Singapore 417921			
Comments/Instructions			
We have further adjusted the amount to \$20,113.00 which is being deemed fair and reasonable. Under normal circumstances, the repairs period would take around 22 (Twenty- Two) working days . We have not authorised repairs This survey was conducted on "Without Prejudice" basis			

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in order legal proceedings.

S.T. Sim

Licensed Motor Surveyor

Diploma Vehicle Engineering (U.K)

SKYCAM AUTOMOBILE SURVEYOR SERVICES

(Registration No.: 52814962L)

63 Sims Plc #13-207 Singapore 380063

H/P: 97422188/ email: sim@skycam.com.sg

Car No: SLF5544R

Nature of Work and Materials	Repairers Estimate (\$)	Remarks	Revised Amount (\$)
Rear bonnet <i>X R</i>	Distorted	\$ 3,000.00	\$ 3,000.00
Rear bonnet weatherstrip <i>X SVC</i>	Deformed	\$ 450.00	\$ 450.00
Rear bonnet TSI emblem <i>/ Nec</i>	Necessary	\$ 80.00	\$ 80.00
Rear bonnet POLO emblem <i>/ Nec</i>	Necessary	\$ 88.00	\$ 88.00
Rear bonnet VW emblem <i>/ Nec</i>	Necessary	\$ 85.00	\$ 85.00
R/L taillamp assy <i>X SVC</i>	Twisted	\$ 900.00	\$ 900.00
R/R taillamp assy <i>X SVC</i>	Twisted	\$ 900.00	\$ 900.00
R/L taillamp retainer <i>X SVC</i>	Bent	\$ 130.00	\$ 130.00
R/R taillamp retainer <i>X SVC</i>	Bent	\$ 130.00	\$ 130.00
Rear end panel <i>X SVC</i>	Bent	\$ 2,000.00	\$ 2,000.00
Rear end panel top tray garnish <i>X SVC</i>	Bent	\$ 350.00	\$ 350.00
Rear bonnet lock <i>X SVC</i>	Bent	\$ 650.00	\$ 650.00
Rear bonnet lock catch <i>X SVC</i>	Bent	\$ 250.00	\$ 250.00
Rear bumper <i>/ CRU</i>	Bent	\$ 3,000.00	\$ 3,000.00
Rear bumper reinforcement <i>X SVC</i>	Bent	\$ 1,500.00	\$ 1,500.00
Rear bumper LH bracket <i>X SVC</i>	Broken	\$ 150.00	\$ 150.00
Rear bumper RH bracket <i>X SVC</i>	Bent	\$ 150.00	\$ 150.00
Rear bumper LH reflector <i>X SVC</i>	Twisted	\$ 250.00	\$ 250.00
Rear bumper RH reflector <i>X SVC</i>	Twisted	\$ 250.00	\$ 250.00
Rear exhaust silencer <i>X SVC</i>	Twisted	\$ 1,500.00	\$ 1,500.00
	Sub-Total A	\$ 15,813.00	\$ 15,813.00
S/Nett			
Reverse sensor <i>/ short</i>		\$ 480.00	\$ 480.00
Bumper clips <i>/ Nec</i>		\$ 200.00	\$ 200.00
	Sub-Total B	\$ 200.00	\$ 200.00
	Parts Grand Total	\$ 16,013.00	\$ 16,013.00

SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #13-207 Singapore 380063

Vehicle No: SLF5544R

Model: Volkswagen/Polo 1.2 Auto

A. Labour Charge

S/no	Job Description	Repairer's Estimate	Revised Estimate
1	To labour charge for cutting out, removing rear bumper and end panel to facilitate replacement of damaged parts	\$ 3,000.00	\$ 2,000.00 400
2	To respray rear bonnet, end panel, spare tyre panel and rear bumper	\$ 2,000.00	\$ 1,800.00 400
3	To remove and install upholstery and rear seat out to facilitate repairs and replacement of damaged parts	\$ 400.00	\$ 300.00 30
	Total Labour	\$ 5,400.00	\$ 4,100.00
	Grand Total	\$ 21,413.00	\$ 20,113.00

$$\begin{array}{r}
 1,186 \\
 - 109 \\
 \hline
 P = 1,067.4 \\
 M = 230 \\
 L = 830 \\
 \hline
 2,127.4 \\
 - 20\% \\
 \hline
 1,701.92
 \end{array}$$

415
\$1,700
3 days

830