

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559N GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

Due

19/7/20

14/7/2020

Sony & repair



08 JUL 2020

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55468 Page No. : 1 of 5
 Date Estimated : 08/07/2020
 Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -

Yang Fei Jonathan
 3 Berwick Drive

Singapore
 Singapore 559894

- ACCOUNT - 40000

Cash Sales - Service
 Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ929K	WBA8E36020NU82564	28/02/2018	318i	0

DESCRIPTION

VALUE

To replace rear bumper include remove attachment etc

~~850 1,275.00~~

To spray rear bumper

~~934 1,088.00~~

To check electrical wiring systems and lightings at the rear section for proper function.

~~150 177.00~~

To replace rear exhaust silencer including alignment system and conduct checks for leak.

~~XAN? 451 521.00~~

Sundries.

~~80? 150.00~~

Total Labour 1: 3,171.00

DESCRIPTION	QTY	PRIC	VALUE
RUBBER MOUNTING ? xsvl	2	17.70	35.40
TAILPIPE TRIM CHROME svl /	1	123.40	123.40
REAR SILENCER ? xsvl	1	1,020.20	1,020.20
CLAMPING BUSH D=58MM ? xan	1	59.45	59.45
RR BUMPER BOTTOM REINFORCEMENT ? xsvl	1	72.65	72.65
REAR BUMPER CENTRE GUIDE ? xsvl	1	55.75	55.75
REAR BUMPER CARRIER (ECE) ? xsvl	1	470.25	470.25
REAR BUMPER TOWING EYE COVER PRIMED XAN	1	43.50	43.50
TRIM STRIP CHROME ca /	1	133.85	133.85
REAR BUMPER PANEL PRIMED (LINES) de -	1	1,178.85	1,178.85
(S/L) LH PROTECTION FOIL ? xsvl	1	10.70	10.70
(S/L) RH PROTECTION FOIL ? xsvl	1	10.70	10.70
SENSOR WIRE FOR SMART OPENER TOP ? xsvl	1	46.30	46.30
SENSOR WIRE FOR SMART OPENER BOTTOM ? xsvl	1	50.90	50.90
DECOUPLING RING PDC TORQUE CONVERTE ? xsvl	4	5.10	20.40
ULTRASONIC SENSOR (JATOBA MET) ? xsvl	4	370.00	1,480.00

Total Parts : 4,812.30

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55468
 Date Estimated : 08/07/2020
 Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ929K	WBA8E36020NU82564	28/02/2018	318i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 14/07/2020 @ 1400 Excess S\$ _____

Surveyor's Name Rahul Sign _____

Surveyor's Tel 90060068 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days



Labour 1	:	3,171.00
Parts	:	4,812.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	558.83

Grand Total

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 55468**
Date Estimated : **08/07/2020**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -

Yang Fei Jonathan
3 Berwick Drive

Singapore
Singapore 559894

- ACCOUNT - **303**

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ929K	WBA8E36020NU82564	28/02/2018	318i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper include remove attachment etc	850.00		850.00
To spray rear bumper	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
# To remove and install tailpipe trim chrome including rear exhaust silencer alignment and conduct checks for leak.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TAILPIPE TRIM CHROME	123.40	1.00		123.40
TRIM STRIP CHROME	133.85	1.00		133.85
REAR BUMPER PANEL PRIMED (LINES)	1,178.85	1.00		1,178.85
# SET MOUNTING PDC/PMA SENSOR REAR	67.30	1.00		67.30
# (DG/SL) ADHESIVE SET K6	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	2,164.00
Total Parts :	1,556.45
Total Labour & Parts :	3,720.45
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,720.45
GST @7%:	260.43
Grand Total :	3,980.88

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 55468**
Date Estimated : **08/07/2020**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -

Yang Fei Jonathan
3 Berwick Drive

Singapore
Singapore 559894

- ACCOUNT - **303**

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ929K	WBA8E36020NU82564	28/02/2018	318i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and install tailpipe trim chrome including rear exhaust silencer alignment and conduct checks for leak.	150.00		150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SET MOUNTING PDC/PMA SENSOR REAR nec/	67.30	1.00		67.30
# (DG/SL) ADHESIVE SET K6 nec/	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	150.00
Total Parts :	120.35
Total Labour & Parts :	270.35