



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007104
INV Date 20/10/2020
Reference CC4/FCI20007167/R1ka3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SGJ 929K
Insured Veh. SHA 1959C
Claim No. D20002717MFSH/1
Policy No. D-20094922MFSH
Accident Date 07/07/2020
Inspection Date 14/07/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20007167/R1ka3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 20-10-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1959C	Veh. Inspected	SGJ 929K
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20002717MFSH/1	Excess (\$)	0.00
Assign From	VIC	Assign Date	09/07/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 318I LED NAV	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBA8E36020NU82564	Colour	GREY
Odometer	22616	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/07/2020	Inspection Date	14/07/2020
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 929K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
2	RUBBER MOUNTING (SN)	SERVICEABLE	35.40	-
1	TAILPIPE TRIM CHROME (SN)	SCRATCHED	123.40	123.40
1	REAR SILENCER (SN)	SERVICEABLE	1,020.20	-
1	CLAMPING BUSH D=58MM (SN)	NOT NECESSARY	59.45	-
1	RR BUMPER BOTTOM REINFORCEMENT (SN)	SERVICEABLE	72.65	-
1	REAR BUMPER CENTRE GUIDE (SN)	SERVICEABLE	55.75	-
1	REAR BUMPER CARRIER (ECE) (SN)	SERVICEABLE	470.25	-
1	REAR BUMPER TOWING EYE COVER PRIMED (SN)	NOT NECESSARY	43.50	-
1	TRIM STRIP CHROME (SN)	CRACKED	133.85	133.85
1	REAR BUMPER PANEL PRIMED (LINES) (SN)	DEFORMED	1,178.85	1,178.85
1	(S/L) LH PROTECTION FOIL (SN)	SERVICEABLE	10.70	-
1	(S/L) RH PROTECTION FOIL (SN)	SERVICEABLE	10.70	-
1	SENSOR WIRE FOR SMART OPENER TOP (SN)	SERVICEABLE	46.30	-
1	SENSOR WIRE FOR SMART OPENER BOTTOM (SN)	SERVICEABLE	50.90	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	SERVICEABLE	20.40	-
4	ULTRASONIC SENSOR (JATOBA MET) (SN)	SERVICEABLE	1,480.00	-
1	SET MOUNTING PDC /PMA SENSOR REAR (SN) (ADDITIONAL)	NECESSARY	67.30	67.30
1	(DG/SL) ADHESIVE SET K6 (SN) (ADDITIONAL)	NECESSARY	53.05	53.05
			5,082.65	1,636.45
<u>LABOUR</u>				
TO REMOVE AND INSTALL TAILPIPE TRIM CHROME INCLUDING REAR EXHAUST SILENCER ALIGNMENT AND CONDUCT CHECK FOR LEAK.(ADDITIONAL)			150.00	150.00
TO REPLACE REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC.			1,275.00	850.00
TO SPRAY REAR BUMPER .			1,038.00	934.00
TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION .			177.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	NOT NECESSARY	531.00	-
			3,171.00	2,084.00
GRAND TOTAL			8,253.65	3,720.45
RECOMMENDED COST OF REPAIRS				3,720.45

Report Ref No. CC4/FCI20007167/R1ka3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Payco Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGJ 929K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGJ 929K

RE-INSPECTION

