

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 40948**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0486/2020/NS  
**Date** : 9-Jul-20

**Vehicle NOT IN workshop. Please arrange for survey.**

**Your insured veh no : SLR 7189 G**

### **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Hui Kam Lung  
**Address** : 68 Bayshore Road  
#26-04  
Singapore 469986  
**Telephone** : (HP) +65 91287128  
**Type of Claim** : Third Party Claims  
**Policy No.** : 2070057810  
**Vehicle No** : **SMT 1806 B**  
**Model Code** : Audi Q3 Sportsback 1.4 TFS  
**Model / Year** : 30/3/2020  
**Engine No** : CZD 891683  
**Chassis No** : WAUZZZF37L1078502  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 9-Jul-20  
**Place of Accident** : New Opera Estate Primary School At Fidelio Street

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMT 1806 B

S/n	Nature of Jobs	Estimated Charges	Survivor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$ 280.00 ✓	×
2	To dismantle and reinstall front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ <del>1,200.00</del> 500 ✓	×
3	To respray front bumper, rhs front fender and both wheel arch trims. ✓	\$ <del>3,000.00</del> 950 ✓	×
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	×
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 4,672.00</u></b>	

*Fender 550  
Wheel Cover x 2  
= 200 x 2 = 400*

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMT 1806 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT WHEEL COVER - LH / RH <i>RH ut, LH nec</i>	2 \$ 1,010.00 ✓	✗ Not consistent
2	SUNDRIES <i>have new</i>	\$ 100.00 ✗	✗ Not consistent
<b>TOTAL SPARE PARTS</b>		<b>: \$ 1,110.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 4,672.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 5,782.00</b>	

All charges are not inclusive of GST.  
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Adrian S  
**Surveyed Date** : 16/07/20  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : Not Authorised, 03 Days.

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant