

# 振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6 #01-40/#01-63 Autobay Singapore 417883  
Tel: 6747-4810 6741-0879  
Fax: 6745-5018  
[cmm@cmm.sg](mailto:cmm@cmm.sg)  
Reg. No. 20561400X

## ESTIMATE

Our Ref: EST148/20/Quote

Your Ref: To Be Advised

*Yonne.*

8-Jul-20

*Independent.*

**Certis CISCO Auxiliary Police Force Pte Ltd**

20 Jalan Afifi

Cisco Centre

Singapore 409179

**Attn: Motor Claims Department**

Dear Sir/Ms

**Re: Estimated cost of repair to vehicle no: RU6857G**

Date of accident: 26/06/2020

Parts supply:

|                                                |                 |                |
|------------------------------------------------|-----------------|----------------|
| 1 pc Tailgate <i>Dented</i>                    | S\$             | 1,637.80 ✓     |
| 2 pcs Tailgate hinge @\$124.00 <i>new</i>      |                 | 248.00 ✗       |
| 2 pcs Tailgate absorber @\$315 <i>new</i>      |                 | 630.00 ✗       |
| 1 pc Tailgate emblem <i>new</i>                |                 | 49.30 ✓        |
| 1 pc Tailgate inner lock <i>Dented</i>         |                 | 264.70 ✓       |
| 1 pc Tailgate weatherstrip <i>new</i>          |                 | 326.00 ✗       |
| 1 pc Rear bumper <i>Dented</i>                 | <i>2892.80.</i> | 357.50 ✓       |
| 8 pcs Rear bumper clips @\$5.00 <i>new</i>     |                 | 40.00 ✓        |
| 2 pcs Rear bumper retainer @\$48.50 <i>new</i> | <i>2169.60</i>  | 103.00 ✓       |
| 1 pc Rear end panel <i>Dented</i>              |                 | 440.50 ✓       |
| 1 pc Rear end panel garnish <i>new</i>         |                 | 233.70 ✗       |
|                                                |                 | <hr/> 4,330.50 |
|                                                | less 25%        | <hr/> 1,082.63 |
|                                                |                 | <hr/> 3,247.87 |

S/Nett items:

|                                           |            |                    |
|-------------------------------------------|------------|--------------------|
| 1 set Reverse sensor <i>Dented</i>        | <i>486</i> | 250.00 <i>20</i>   |
| 1 pc Rear windscreen gum <i>new</i>       |            | 80.00 <i>60</i>    |
| 1 pc Tailgate sticker - CERTIS <i>new</i> |            | 60.00 ✓            |
| 1 pc Tailgate sticker - CERTIS CISCO      |            | 60.00 ✓            |
| 1 pc Tailgate sticker - AUXILIARY POLICE  |            | 60.00 ✓            |
| 1 pc Rear no plate <i>new</i>             |            | 45.00 <i>30</i>    |
| 1 pc Rear no plate seal <i>new</i>        |            | 18.00 ✓            |
|                                           |            | <hr/> S\$ 3,820.87 |

# 振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6 #01-40/#01-63 Autobay Singapore 417883

Tel: 6747-4810 6741-0879

Fax: 6745-5018

cmm@cmm.sg

Reg. No. 20561400X

## ESTIMATE

### Re: Estimated cost of repair to vehicle no: RU6857G

Date of accident: 26/06/2020

#### S/Nett items:

Balance b/f:

|                                                     |       |    |     |          |
|-----------------------------------------------------|-------|----|-----|----------|
| 1 pc Tailgate sticker - Green Disc                  | Neu   | 95 | S\$ | 3,820.87 |
| 1 pc Tailgate sticker - 60km/h                      | Neu   |    |     | 20.00 ✓  |
| 1 pc Tailgate sticker - Emergency door pull to open | Neu   |    |     | 10.00 ✓  |
| 1 pc Tailgate sticker - TOYOTA                      | } Neu |    |     | 15.00 ✓  |
| 1 pc Tailgate sticker - HIACE                       |       |    |     | 25.00 ✓  |
|                                                     |       |    |     | 25.00 ✓  |

#### Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as-mentioned above etc.

To respray affected part.

To check wiring.

To remove & refit rear windscreen

To apply underseal

To remove & refit reverse sensor.

Towing from Sats to workshop, workshop to Vicom & back to Sats @\$80

|      |                       |
|------|-----------------------|
|      | <del>700.00</del> 600 |
| 1690 | <del>750.00</del> 600 |
|      | 30.00 ✓               |
|      | 100.00 ✓              |
|      | 60.00 ✓               |
|      | 60.00 ✓               |
|      | 240.00 ✓              |
| S\$  | <u>5,855.87</u>       |

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

08/07/20.

PF 06 days

L/S

total: 4440.60

L/S: 3550