

AutoSoon Pte Ltd

17G Sin Ming Drive #01-10

Sin Ming AutoCare Singapore 575721

Tel No. : 6452 6657 Fax No. : 6451 4618

E-Mail : autosoon1@gmail.com

Tax Reg. No. : 200709808N Buss. Reg. No. : 200709808N

TOH CHEK KHIANG

473-C Upper Serangoon Crescent

#18-349

Singapore 533473

Contact : 9843 8305

Estimate : ES000445

Date : 11/07/2020

Vehicle Num. : SMT 3016 B

Make/Model : TOYOTA CAMRY HYBRID 2.5G CVT-20

Chassis/Eng# : JTNB23HKX03056886

Accident Date : 11/07/2020

Claim No. : TP: FWD

Reference : TP/01/07/20

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Radiator grille assy - <i>Cut</i>		688.30
2.	1	Bumper facial - <i>CLA</i>		591.30
3.	10	Bumper facial clips - <i>REC</i>	5.00	50.00
4.	1	Bumper lower grille - <i>x</i>		763.30
5.	1	Bumper reinforcement assy - <i>?</i>		355.30
6.	1	O/s bumper retainer assy - <i>Re</i>		97.42
7.	1	O/s fog lamp cover - <i>?</i>		68.30
8.	1	O/s parking sensor assy - <i>DM</i>		472.10
9.	1	O/s parking sensor bezel - <i>REC</i>		26.00
10.	1	O/s head lamp assy - <i>Cut</i>		2,690.00
11.	1	O/s fender assy - <i>Buc</i>		689.20
12.	1	O/s fender badge - <i>REC</i>		39.30
13.	1	O/s fender inner shield - <i>Re</i>		240.55
14.	8	O/s fender inner shield clip - <i>REC</i>	5.00	40.00
15.	1	O/s alloy wheel assy - <i>Cut</i>		2,300.00
16.	1	O/s wheel bearing assy - <i>DM</i>		139.26
17.	1	O/s wheel bearing hud - <i>?</i>		467.80
18.	1	O/s wheel knuckle arm - <i>?</i>		501.41
19.	1	O/s wheel lower arm assy - <i>?</i>		528.80
20.	1	O/s wheel shock absorber - <i>?</i>		548.00
21.	1	O/s wheel shock absorber top mounting - <i>?</i>		193.51
List TotalS\$:				11,489.85
25.00% Discount S\$:				2,872.46
				8,617.39

CONTINUE / ...

Ltd

Singapore 575721
 Fax No. : 6451 4618
 n1@gmail.com
 . 200709808N Buss. Reg. No. : 200709808N

CHEK KHIANG
 /3-C Upper Serangoon Crescent
 #18-349
 Singapore 533473

Contact : 9843 8305

Estimate : ES000445

Date : 11/07/2020
 Vehicle Num. : SMT 3016 B
 Make/Model : TOYOTA CAMRY HYBRID 2.5G CVT-2020
 Chassis/Eng# : JTNB23HKX03056886
 Accident Date : 11/07/2020
 Claim No. : TP: FWD
 Reference : TP/01/07/20
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
1		To rewire affected section and refocus head lamp beam	50.00	50.00 30
1		To computer check/readjust wheel realignment in repair.	80.00	80.00 60
1		To replace wheel control arms, kunckle, bearing and hud include shock absorber, mounting in repair	180.00	180.00 ?
1		To putty and respray affected panels in repair.	1,280.00	1,280.00 800 90
1		To undersealing damaged panels with anti rust	80.00	80.00 60
1		To remove damaged portion, restraighten/recondition o/s wheel housing. Panel beat head lamp panel, support panel and all affected doors include realign bumper in repair	680.00	680.00 480
Labour Total S\$:				2,350.00

5-6 Days.
 part by part.
 before part photos.



Cheong Kiang - 82880282

13/7/2020

Total S\$: 10,967.39
 GST @ 7% S\$: 767.72
 Amount Due S\$: 11,735.11
 =====

AutoSoon Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: