

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Elaine Cheong	Date:	16 Jul 2020

Preliminary Advice

Insured Vehicle No	: SLQ8080J	Accident Date	: 09/07/2020
TP Vehicle No	: SMT3016B	Assignment Date	: 13/07/2020
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 6
Date of Inspection	: 13/07/2020		
Inspection At	: AUTO SOON PTE LTD (HQ) BLOCK 176 SIN MING DRIVE, #01-10 SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 10,967.39
Revised Amount	:S\$ 7,577.57
Check Items (Estimated)	:S\$ 2,177.34
Total	:S\$ 9,754.91
Lump Sum Repair :S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :