

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Ref:

PRE-REPAIR INSPECTION REPORT

50 RAFFLES PLACE #05-01/06

SOMPO INSURANCE SINGAPORE PL

SINGAPORE LAND TOWERSINGAP

ORE 048623	Date:	30-07-2020	
	Code:	SMO	

CS3/SMO20007205/GUtf3e2

Page No.:1 of 1

			Code: SIVIO	
1.		Policy Particulars	:- (THIRD PARTY CLAIM)	
	Insured Veh.	GBG 9960J	Veh. Inspected	FBP 7790Z
	Policy No.	D19MTPCVE003607	Coverage (\$)	0.00
	Claim No.	CMTD2001521/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	13/07/2020
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA MX KING T150	c.c	150
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MH3UG0750KK023432	Colour	BLUE
	Odometer	31720 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	90/80-17	TIMSUN	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	120/70-17	TIMSUN	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S	BODY.	

5.	General Information			
	Accident Date	25/04/2020	Inspect Date / Time	22/07/2020 (05:00 PM)
	Survey held at	GP MOTORING PTE LTD		
		282 MACPHERSON ROAD SINGAPORE 348607		

5a.		Remarks
		A) THE INCRECTION WAS CONDUCTED ON A WAITHOUT DREILIDICE! DAGIC

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
- THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000

5b. **Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days

Report Ref No. CS3/SMO20007205/GUtf3e2

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.