

# C L APPRAISER PTE LTD

Vehicle Registration No: YN 7916 S

Our Ref No: TWG/02/2006/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 9,100.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Disclaimer**



*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**C L APPRAISER PTE LTD**





Cheong K. H  
Automotive Appraiser







INSURANCE  
EIGHT  
APPRAISAL



APPRAISER P  
L  
S

SUCCÈS  
ENTREPRE  
Platinum Car

NGH