



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20004343/R1tf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 20-07-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3445U	Veh. Inspected	GBH 9637M
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20030265	Excess (\$)	0.00
Assign From	DERRICK TAN	Assign Date	13/07/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTFAT35Y20K211742	Colour	BLUE
Odometer	66711	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/70 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/70 R15	YOKOHAMA	6 mm
R/H Rear Tyre	155 R12C (D)	BRIDGESTONE	4/4 mm
L/H Rear Tyre	155 R12C (D)	BRIDGESTONE	4/4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/03/2020	Inspection Date	31/03/2020
Survey held at	U E MOTOR BLK 3006, UBI ROAD 1 #01-334 SINGAPORE 408700		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------