

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40905

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0484/2020/NS
Date : 9-Jul-20

Vehicle IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name :
Address : Ms Chee Helen
23 Garlick Avenue
Singapore 279654
Telephone : (HP) +65 92388640
Type of Claim : Own Damage Claim
Policy No. : 2100454920-04
Vehicle No : **SFY 230 A**
Model Code : A4 Sedan 1.4 TFSI S
Model / Year : 29/2/2016
Engine No : CVN 002774
Chassis No : WAUZZZF4XGA027770
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Jul-20
Place of Accident : Tiong Bahru Multi Storey Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFY 230 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow in vehicle from accident scene.	S/N \$ 280.00	X X
2	To remove and transfer lhs headlight control unit and power module. To carry out calibration.	S/N \$ 350.00	250 ✓
3	To dismantle and reinstall lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 350.00	X.
4	To dismantle and renew front bumper, lhs front fender and bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1000 ✓
5	To respray front bumper, lhs front fender, bonnet and lhs front door.	\$ 3,700.00	1100 ✓
6	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00	✓ ✓
7	To carry out diagnostic check.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		\$ 7,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFY 230 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Deformed</i>	\$ 2,010.00	✓ 116.00
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 269.00	X
3	FRONT BUMPER SECURING STRIP <i>new Pangs.</i> 2	\$ 67.00	✓ 55.68
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 198.00	X
5	FRONT BUMPER AIR GUIDE - LH <i>Crushed</i>	\$ 59.00	✓ 49.52
6	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$ 344.00	X
7	FRONT BUMPER GUIDE SECTION - LH <i>Damaged</i>	\$ 34.00	✓ 27.12
8	FRONT FENDER - LH <i>Damaged</i>	\$ 722.00	✓ 577.60
9	FRONT FENDER ATTACHMENT PARTS	\$ 190.00	X
10	FRONT FENDER CLOSING ELEMENT - LH <i>Damaged</i>	\$ 47.00	✓ 39.20
11	FRONT FENDER BRACKET - LH <i>Best</i>	\$ 33.00	✓ 26.24
12	DEFORMATION ELEMENT BRACKET - LH <i>Best</i>	\$ 46.00	✓ 38.80
13	FRONT FENDER BRACKET <i>Best</i>	\$ 32.00	✓ 24.96
14	FRONT FENDER BRACE <i>Best</i>	\$ 112.00	✓ 93.60
15	FRONT FENDER CLOSING ELEMENT - LH ?	\$ 31.00	? X
16	WHEEL HOUSING LINER - LH <i>torn</i>	\$ 226.00	✓ 180.40
17	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 86.00	? X
18	WHEEL SPOILER <i>Crushed</i>	\$ 69.00	✓ 57.76
19	WHEEL SPOILER TRIM - LH ?	\$ 33.00	?
20	STONE CHIP GUARD <i>new</i>	\$ 48.00	✓ 37.92
SUB TOTAL SPARE PARTS		: \$ 4,656.00	

Resurveyed
15/07/20
SPS

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFY 230 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	FENDER LEDGE COVER - UPPER <i>del</i>	\$ 29.00	✓ 23.20
22	FENDER LEDGE COVER - LOWER <i>missing</i>	\$ 21.00	✓ 16.72
23	BONNET <i>Men</i>	\$ 2,634.00	x
24	BONNET ATTACHMENT PARTS <i>Men</i>	\$ 116.00	+
25	BONNET IMPACT PROTECTION - LH / RH / CENTRE <i>3</i>	\$ 78.00	+
26	LED HEADLIGHT - LH <i>ut</i>	\$ 7,321.00	✓ 5851.80
27	LIFT CYLINDER - LH ?	\$ 198.00	?
28	LIFT CYLINDER CORRUGATED PIPE <i>Men</i>	\$ 88.00	x
29	FRONT ALUMINIUM RIM - LH <i>ut</i>	\$ 660.00	✓ 527.60
30	SUNDRIES ?	\$ 300.00	? 97.44
TOTAL SPARE PARTS		: \$ 16,101.00	
TOTAL LABOUR CHARGES		: \$ 7,952.00	
GRAND TOTAL		: \$ 24,053.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lj*
Surveyed Date : *13/07/20*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 Days*

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant