

ESIIMATE

DATE 3.7.2020

YP7989X FUSO FEB50

No	Qty	PARTICULAR	SPECAIL NETT	AMOUNT S\$
1	1	CARGO BOX PILLAR REAR RH	xr	1,520.00
2	1	DOOR PANEL REAR RH	xr	1,422.00
				<u>\$ 2,942.00</u>

No	LABOUR & MISCELLANEOUS:	AMOUNT S\$
1	To remove damaged body parts with all necessary components/attach- ments apply hot-works where necessary straighten door pillar,repair,reshape dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,000.00 <i>400</i>
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	<i>✓</i> 400.00
		<u>\$ 1,400.00</u>

Repair dy - 2 days

p/p.

After painting photo.

Sun Pin (Lkt)

14/07/2020.

TP without prejudice.

Sunpin@LkkAuto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: