

ASS. REC. BY:

REF:

1002 / 2000 7222 / Ks3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

29k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4-5

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

21/7 11:00 823506 Car found

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Veh No:

SL 36894

Yr Regn:

08 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c

1497

Colour

m. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

13 5044

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMG88509S 201711

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

7/7/20

D.O.I.

13/7/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD

NO. 36
ROBINSON RD #16-01
CITY HOUSE
SINGAPORE 068877

Contact : 97259944

Fax No. : 65073849

Estimate : QUOT202007-000252(00)

Date : 09/07/2020

Vehicle No. : SGL3689Y

Make/Model : HONDA JAZZ 1.5L AT ABS DAB
HID 2WD 5DR

Mileage (km) : 0

Chassis No. : JHMGE88509S201711

Accident Date : 07/07/2020 00:00:00

Claim No. : SHA3260X

Reference : JO202007-0309

Policy No. : GA531687/1

*Not authorized
L1 Pay @ 2350/h
Mercury After Paint
4-5 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Tailgate	1.0	771.50	771.50
2	Tailgate glass moulding	1.0	36.80	36.80
3	Tailgate lock	1.0	189.00	189.00
4	Tailgate striker	1.0	37.50	37.50
5	Tailgate weatherstrip	1.0	92.30	92.30
6	Tailgate damper	2.0	136.20	272.40
7	Tailgate stopper	2.0	22.00	44.00
8	Tailgate emblem - JAZZ	1.0	32.20	32.20
9	Rear bumper	1.0	460.30	460.30
10	Rear bumper retainer	2.0	18.50	37.00
11	Rear bumper lower cover	1.0	145.00	145.00
12	Rear Bumper clips	10.0	3.90	39.00
13	Tail lamp	2.0	226.20	452.40
14	Taillamp clip	2.0	4.50	9.00
15	Rear end panel	1.0	296.50	296.50
16	Rear end panel top garnish	1.0	60.80	60.80
17	Rear floor deck foam	1.0	114.60	114.60
18	Rear fender trim	2.0	203.20	406.40
19	Trunk floor panel	1.0	737.00	737.00
List Total :				4,233.70
20% Discount S\$				846.74
				3,386.96
SPECIAL NET :				
1	Tailgate glass sealant	1.0	40.00	40.00
2	Reverse sensor	1.0	250.00	250.00
SPECIAL NET Total S\$:				290.00
LABOUR :				
	* To remove and refit rear windscreen glass	1.0	100.00	100.00
	* To remove and refit trims and upholstery	1.0	120.00	120.00
	* To check wiring and lighting	1.0	45.00	45.00
	* To supply panel sealant and to seal off all weld spot seam and gaps	1.0	80.00	80.00
	* To spray rubberized under-coating	1.0	60.00	60.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD #16-01

CITY HOUSE

SINGAPORE 068877

Contact : 97259944

Fax No. : 65073849

Estimate : QUOT202007-000252(00)

Date : 09/07/2020

Vehicle No. : SGL3689Y

Make/Model : HONDA JAZZ 1.5L AT ABS DAB
HID 2WD 5DR

Mileage (km) : 0

Chassis No. : JHMGE88509S201711

Accident Date : 07/07/2020 00:00:00

Claim No. : SHA3260X

Reference : JO202007-0309

Policy No. : GA531687/1

S/No	Particular	Quantity	Unit Price	Amount S\$
	-To knock jackout damaged parts, panel beating,welding, align, refix and to renew accident parts	1.0	1,000.00	<i>500</i> 1,000.00
	- Spray painting on affected & replace parts	1.0	1,200.00	<i>600</i> 1,200.00
				<u>2,605.00</u>

E. & O.E.

Total S\$: 6,281.96

GST 7% S\$: 439.74

Amount Due S\$: 6,721.70

for CITY AUTO PTE LTD