CSh o C	
Kenneth REF. SMSG/	2000 726 Kof3
A	SSIGNMENT
From:	
EstImated Cost:	Veh No: SIM 4633EYr Regn: 01, 08 Type: M.Cost M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
10 Inspect Vehicle No:	Make: Tay Allian c.c 1886
at Workshop m/s Bistray	Colour M.Black AC: Insured / Std / NI / NA
of	Sp.Reading 253915 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: N 77260 · 3035799
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: (Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Ingreer / Jammed / Leaked / Burnt or
	Modi: NII / S/Rim / STDA/Rim or
(Policy Condition)	Tyre Size: F: /75/65R15
Pumark: The year had assessed to	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal. or Market Value:	
10404 11 15	2Rel 2
	/Bal. 3 mm L/Bal. 3 mm
Est. Repairs: 05 days Res.: Yes or No	DA. 9/7/20 D.O.I. 14/7/2020
Lum Sum: 20 % 3 Val.: Yes or No	urvey held at
CA / REV / REP. / 24 HRS	es. of Damages : Frt Read   O/S   N/S   U/C   Rooftop or
Vehicle: IN / OUT	
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
KENNETH CONFIRMED L/S \$ 4	4,500.00/5 DAYS WITH MR. LEE:
(\$ 2,099.76/RED - 32%)	
Date/Timo, File Pass 107 11/09/2020 : Prell. Report Days Of	f Repair: 5
1) TYPIST : Final Report Resurve	by No. of Trip: 1 Survey Fee:
	Transportation:
Add Fee: :	ite Insp (\$ ) s · RS _ SI
	terview (\$ ), F.e.'s
Report Format:	ech Invs (\$ ) Others
Lump Sun / I.B.I: (\$ \$ 4,500.00 L/S ) W.	eekend (\$
	107AL

Scanned wi

## **BIFROST AUTO PTE LTD**

REPAIR ESTIMATE

9-Jul-20

Not Normarin

DATE:

MODEL:

**TOYOTA ALLION** 

INSURANCE: MSIG
ALWAY After Pains

			. 1000	- LIGT BRICE	day,
DESCRIPTION	and the second of the second o	QTY	UNIT PRICE		_
RERA BUMPER		1	400.00	\$968.40	
REAR BUMPER RETAINER	NISE		\$96.80		
REAR BUMPER REFLECTOR	SVC	2	\$68.90		H _
REAR BUMPER CLIPS	5 - 14 S	10	\$5.90		4000
REAR END PANEL		1		\$584.60	1-
REAR END PANEL GARNISH		1		p// \$169.40	1.
TAIL LAMP	CN		\$421.40	\$842.80	15
TAIL LAMP PANEL	R	2	\$169.80	\$339.60	l ′ .
REAR BOOT LID		1		<b>4</b> \$968.70	
REAR BOOT LOOK		1		\$475.40	
REAR BOOT HINGE		2	\$96.50	N \$193.00	٨,
REAR BOOT RUBBER		1		m \$268.40	-
REAR BOOT OUTER CHROME		1		\$290.40	
REAR BOOT ALLION EMBLEM		1		ke \$76.80	1-
REAR BOOT A15 EMBLEM		1	/	جر \$56.80	
28 06					REFE
					3
	*				
SUB TOTAL	,**			\$5,624.70	
.ESS 25%				\$1,124.94	K-1 - 28:
DISCOUNTED TOTAL	LKK Auto Consultants her	Co notify		\$4,499.76	1
					1
REAR BUMPER SENSOR	To display damaged	painting		\$200.00	
REAR NUMBER PLATE	Parts prices are subject to configurations.  Third parts.	my resurvey		Su \$40.00	1 x
			.		1
UB TOTAL	Sunnlementary it	ed	-	\$240.00	1
	is subject to final approval from n	esurveyed and		42 10100	
	Acknowledged by Repairer	Surdice Company	-		٠.
abour Charge	Signature:		1		
anel Beating	Date.	1	\$750.00	\$750.00	650
pray Painting Charge		-	\$1,000.00	\$1,000.000	8001
firing Charge		1	\$30.00		
uff Kote			<b>აა</b> 0.00	\$30.00	201
		_	000.55	\$0.00	
nti-rust		1	\$80.00	\$ 80.00	601
OTAL LABOUR				\$1,860.00	
STIMATE TOTAL					

Scanned wi