

ASS. REC. BY:

REF:

14 / 2000 72771kg

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Yee

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKR 1353A Yr Regn: 01, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or Wagon

Make: Mazda B180 c.c. 1595

Colour: N. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 88538 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 24 62422 J 289599

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/35R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 9/7/20 D.O.I. 14/7/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Got injury</u>
<u>318</u>	<u>11 Sep @ 58501 Continental</u>

Date/Time, File Pass to? : Prell. Report : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	
\$ - RS. \$	
Fuel	
Others	
TOTAL	

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

Report Format : _____
Lump Sum / I.B.I: (\$ _____)



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteltd@gmail.com
 Registration No: 201719251W GST No: 201719251W

M/S : India International Insurance Pte Ltd
 64 Cecil Street
 #05-01 IOB Building
 Singapore 049711

Estimate No: **ES2000059**
 Date: 13 Jul 2020
 Policy No:
 Veh Reg No: **SKR1353A**
 Make/Model: **MERCEDES BEN B180 (R16 BI)**
 Chassis No: **WDD2462422J289599**
 Engine No: **27091030510960**
 Reg. Date: **20/01/2015**

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 09/07/2020
 TP Veh Reg No: SHD3364P

NOT AUTHORIZED
U/Sing @?
Resony After Repair
5 days

Estimate Repair Cost to Vehicle No :SKR1353A

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Spare Parts				
1 FRONT DOOR - RH <i>1930</i>	1,940.20	1 PC	<i>By</i> 1,940.20	—
2 FRONT DOOR GLASS CHANNEL - RH	182.10	1 PC	<i>Sm</i> 182.10	X
3 FRONT DOOR CHECKER - RH	238.10	1 PC	<i>Sm</i> 238.10	X
4 FRONT DOOR HINGE LOWER - RH	198.10	1 PC	<i>n</i> 198.10	X
5 FRONT DOOR HINGE UP - RH	198.10	1 PC	<i>n</i> 198.10	X
6 FRONT DOOR INNER LOCK - RH	655.00	1 PC	<i>n</i> 655.00	X
7 FRONT DOOR OUTER MOULDING - RH	388.00	1 PC	<i>Sm</i> 388.00	X
8 FRONT DOOR REGULATOR GEAR - RH <i>420</i>	630.00	1 PC	<i>Di?</i> 630.00	n
9 FRONT DOOR REGULATOR GEAR MOTOR - RH	704.00	1 PC	<i>Sm</i> 704.00	n
10 FRONT DOOR RIVETS	10.00	10 PCS	<i>na</i> 100.00	—
11 FRONT DOOR STRIKER - RH	108.10	1 PC	<i>na</i> 108.10	—
12 FRONT DOOR TRIM BOARD - RH	1,380.80	1 PC	<i>Sm</i> 1,380.80	X
13 FRONT DOOR WEATHERSTRIP - RH	288.00	1 PC	<i>na</i> 288.00	<i>50/100</i>
14 REAR DOOR - RH <i>1801</i>	1,880.50	1 PC	<i>By</i> 1,880.50	—
15 REAR DOOR CHANNEL - RH	182.10	1 PC	<i>Sm</i> 182.10	X
16 REAR DOOR CHECKER - RH	238.10	1 PC	<i>Sm</i> 238.10	X
17 REAR DOOR HINGE LOWER - RH	198.10	1 PC	<i>n</i> 198.10	X
18 REAR DOOR HINGE UP - RH	198.10	1 PC	<i>n</i> 198.10	X
19 REAR DOOR LOCK - RH	655.00	1 PC	<i>n</i> 655.00	X
20 REAR DOOR OUTER MOULDING - RH	90.00	1 PC	<i>Sm</i> 90.00	X
21 REAR DOOR REGULATOR GEAR - RH	568.00	1 PC	<i>Sm</i> 568.00	X
22 REAR DOOR REGULATOR GEAR MOTOR - RH	608.00	1 PC	<i>Sm</i> 608.00	X
23 REAR DOOR RIVETS	10.00	10 PCS	<i>na</i> 100.00	—
24 REAR DOOR STRIKER - RH	98.10	1 PC	<i>na</i> 98.10	—
25 REAR DOOR TRIM BOARD	1,280.10	1 PC	<i>Sm</i> 1,280.10	X
26 REAR DOOR WEATHERSTRIP - RH	288.00	1 PC	<i>na</i> 288.00	<i>50/100</i>
27 ROCKER PANEL GARNISH - RH	868.50	1 PC	<i>msc003</i> 868.50	n
28 ROCKER PANEL GARNISH CLIP	8.00	10 PCS	<i>na</i> 80.00	n
			14,343.10	14,343.10
Labour				
29 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	<i>5500</i>
30 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	<i>8000</i>
31 TO REMOVE 2 PCS DOOR COMPONENTS	160.00	1 JOB	160.00	<i>1200</i>
32 WHEEL ALIGNMENT	150.00	1 T	<i>nn</i> 150.00	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteLtd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

Estimate No: ES2000059
Date: 13 Jul 2020
Policy No:
Veh Reg No: SKR1353A
Make/Model: MERCEDES BEN B180
(R16 BI)
Chassis No: WDD2462422J289599
Engine No: 27091030510960
Reg. Date: 20/01/2015

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 09/07/2020
TP Veh Reg No: SHD3364P

Estimate Repair Cost to Vehicle No :SKR1353A

Description	U/Price	Quantity	List Price	Amount
33 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	SS 80.00	SS 200
34 COMPUTER DIAGNOSTIC RESET	350.00	1 JOB	SS 350.00	SS 7
			4,340.00	4,340.00
			Total	SS 18,683.10
			Add GST @ 7%	1,307.82
			Total Amount Payable	SS 19,990.92

TOTAL: SINGAPORE DOLLAR NINETEEN THOUSAND NINE HUNDRED NINETY AND CENTS NINETY TWO ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: