



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteLtd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : India International Insurance Pte Ltd
 64 Cecil Street
 #05-01 IOB Building
 Singapore 049711

Estimate No: ES2000059
 Date: 13 Jul 2020
 Policy No:
 Veh Reg No: SKR1353A
 Make/Model: MERCEDES BEN B180 (R16 BI)
 Chassis No: WDD2462422J289599
 Engine No: 27091030510960
 Reg. Date: 20/01/2015

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 09/07/2020
 TP Veh Reg No: SHD3364P

Not Authorized
U/Sing @?
Person After Paint
5 days

Estimate Repair Cost to Vehicle No :SKR1353A

Description	U/Price	Quantity	List Price SS	Amount SS
Spare Parts				
1 FRONT DOOR - RH	1,940.20	1 PC	1,940.20	✓
2 FRONT DOOR GLASS CHANNEL - RH	182.10	1 PC	182.10	X
3 FRONT DOOR CHECKER - RH	238.10	1 PC	238.10	X
4 FRONT DOOR HINGE LOWER - RH	198.10	1 PC	198.10	X
5 FRONT DOOR HINGE UP - RH	198.10	1 PC	198.10	X
6 FRONT DOOR INNER LOCK - RH	655.00	1 PC	655.00	X
7 FRONT DOOR OUTER MOULDING - RH	388.00	1 PC	388.00	X
8 FRONT DOOR REGULATOR GEAR - RH	630.00	1 PC	630.00	?
9 FRONT DOOR REGULATOR GEAR MOTOR - RH	704.00	1 PC	704.00	?
10 FRONT DOOR RIVETS	10.00	10 PCS	100.00	✓
11 FRONT DOOR STRIKER - RH	108.10	1 PC	108.10	✓
12 FRONT DOOR TRIM BOARD - RH	1,380.80	1 PC	1,380.80	X
13 FRONT DOOR WEATHERSTRIP - RH	288.00	1 PC	288.00	50% ✓
14 REAR DOOR - RH	1,880.50	1 PC	1,880.50	✓
15 REAR DOOR CHANNEL - RH	182.10	1 PC	182.10	X
16 REAR DOOR CHECKER - RH	238.10	1 PC	238.10	X
17 REAR DOOR HINGE LOWER - RH	198.10	1 PC	198.10	X
18 REAR DOOR HINGE UP - RH	198.10	1 PC	198.10	X
19 REAR DOOR LOCK - RH	655.00	1 PC	655.00	X
20 REAR DOOR OUTER MOULDING - RH	90.00	1 PC	90.00	X
21 REAR DOOR REGULATOR GEAR - RH	568.00	1 PC	568.00	X
22 REAR DOOR REGULATOR GEAR MOTOR - RH	608.00	1 PC	608.00	X
23 REAR DOOR RIVETS	10.00	10 PCS	100.00	✓
24 REAR DOOR STRIKER - RH	98.10	1 PC	98.10	✓
25 REAR DOOR TRIM BOARD	1,280.10	1 PC	1,280.10	X
26 REAR DOOR WEATHERSTRIP - RH	288.00	1 PC	288.00	50% ✓
27 ROCKER PANEL GARNISH - RH	868.50	1 PC	868.50	?
28 ROCKER PANEL GARNISH CLIP	8.00	10 PCS	80.00	?
			14,343.10	14,343.10
Labour				
29 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	55%
30 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	80%
31 TO REMOVE 2 PCS DOOR COMPONENTS	160.00	1 JOB	160.00	120%
32 WHEEL ALIGNMENT	150.00	1 T	150.00	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteld@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S : India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

Estimate No: ES2000059
Date: 13 Jul 2020
Policy No:
Veh Reg No: SKR1353A
Make/Model: MERCEDES BEN B180 (R16 BI)
Chassis No: WDD2462422J289599
Engine No: 27091030510960
Reg. Date: 20/01/2015

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 09/07/2020
TP Veh Reg No: SHD3364P

Estimate Repair Cost to Vehicle No :SKR1353A

Description	U/Price	Quantity	List Price	Amount	
				SS	SS
33 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	2el	SS
34 COMPUTER DIAGNOSTIC RESET	350.00	1 JOB	350.00	?	
			4,340.00		4,340.00
Total					SS 18,683.10
Add GST @ 7%					1,307.82
Total Amount Payable					SS 19,990.92

TOTAL: SINGAPORE DOLLAR NINETEEN THOUSAND NINE HUNDRED NINETY AND CENTS NINETY TWO ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: