

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20007228/T1ES3Q2

**Date:** 09/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900010112
<b>Claimant</b>		
<b>Vehicle No :</b> SHD7143J	<b>Insured Vehicle No :</b>	SDN93K
Date of Loss: 08/07/2020	Nature of Claim: TP	Claim No: 1008577455SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD7143J		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU689654
Reg. Date:	10/11/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU096307
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,236.04	3,884.76	351.28	8.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,100.00	700.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,036.04</b>	<b>4,984.76</b>	<b>1,051.28</b>	<b>17.42</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>(S\$)</b>	6,036.04	4,000.00	2,036.04	33.73
<b>+ GST 7.00/7.00% (S\$)</b>	422.52	280.00	142.52	33.73
<b>Nett Amount (S\$)</b>	<b>6,458.56</b>	<b>4,280.00</b>	<b>2,178.56</b>	<b>33.73</b>
<b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b>		250.00		
<b>+ Car Rental (5.0 x S\$112.67/day) (S\$)</b>		563.35		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>5,100.84</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,100.00</b>		

### INSPECTION

Date of Assignment: 13/07/2020

Date Inspected: 13/07/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	2,256.40 FL	*2,256.40 FL
2	1		*REAR DOOR RH	Bent	2,201.10 FL	*2,201.10 FL
3	1		*FRONT DOOR HINGE RH/UPP	Repair	44.50 FL	*- FL
4	1		*FRONT DOOR HINGE RH /LOW	Repair	44.50 FL	*- FL
5	1		*FRONT DOOR HANDLE RH	Cracked	36.30 FL	*36.30 FL
6	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	176.80 FL	*- FL
7	1		*FRONT DOOR BLACK PLASIC COVER	Necessary	84.20 FL	*84.20 FL
8	1		*REAR DOOR BLACK PLASTIC COVER	Necessary	84.20 FL	*84.20 FL
9	1		*REAR DOOR HINGE RH/UPP	Repair	53.40 FL	*- FL
10	1		*REAR DOOR HINGE RH/LOW	Repair	53.40 FL	*- FL
11	1		*REAR DOOR CHECK RH	Repair	66.50 FL	*- FL
12	1		*FRT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
13	1		*REAR DOOR APP LOGO	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,256.30</b>	<b>4,817.20</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,020.26	932.44
<b>Total Parts (\$\$)</b>	<b>4,236.04</b>	<b>3,884.76</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	720.00	420.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	REMOVE/REFIX UPHOLSTERY REAR	New	180.00	0.00
4	TRANSFER DOOR PARTS	New	120.00	120.00
5	TUFF KOTE	New	120.00	30.00
6	CHECK LIGHTING	New	60.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>1,800.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >