## **MFORTDELGRO PTE LTD**

## PAIR ESTIMATE\*

HICLE NO

SHD7143J

MAKE

.

MODEL 1-40

DATE 04/26/02 12:00 AM CHIANG/AIG

ODEL	1-40			
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	1 FRONT DOOR RH		The second secon	\$2,256.40
	1 REAR DOOR RH			\$2,201.10 4
	1 FRONT DOOR HINGE RH/ UPP			\$44.50
	1 FRONT DOOR HINGE RH/ LOW			\$44.50 <>
	1 FRONT DOOR HANDLE RH			\$36.30 av
	1 FRONT DOOR OUTER MOULDING RH			\$176.80 📉
	1 FRONTDOOR BLACK PLASIC COVER			\$84.20
	1 REAR DOOR BLACK PLASTIC COVER			\$84.20
	1 REAR DOOR HINGE RH/UPP			\$53.40 %
	1 REAR DOOR HINGE RH/LOW			\$53.40 Cy
	1 REAR DOOR CHECK RH			\$66.50 8
	SUB TOTAL			\$5,101.30
	20.00%		4662.20	\$1,020.26
	DISCOUNTED TOTAL		4662.20 3729.76,	\$4,081.04
			5+19-76.	\$ 1,002.04
	1 FRT DOOR COMFORT LOGO			\$75.00 ~40
	1 REAR DOOR APP LOGO			\$80.00 ~
				\$155.00
	Labour Charge			1
	Panel Beating			\$720.00 42
	Spray Painting Charge	1		\$600.00 500
	Remove /Refix Upholstery rear	1		\$180.00 × 11
	Tranfer door parts			\$120.00
	Tuff Kote		1 1 24 2/	\$120.00   \$0.
	Check Lighting		3729.76	\$60.00 30.
	TOTAL LABOUR		155	\$1,800.00
		-	119842	71,800.00
	ESTIMATE TOTAL		710116	\$6,036.04
			1/5/4000	70,030.04
			4984.76 4984.76 1/584000 ~ 3dugs	
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
	ha annual describe the second of the second			adrituii wiii

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfrín 97495749

Lumpson 13/7/20 e 1/m

tanfrín 0 lkhantonn

03chys

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Inird party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sanature: