

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4

#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809

Tel: 67139400 Fax: 67139415

Email: servicecentre@abwinm9.com Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G

ABWIN 諭輝 M9
Service Centre

Ref: 62563561

ESTIMATED COST: HQQ000351**TO : MS FIRST CAPITAL INSURANCE LIMITED**
ATTN : MOTOR CLAIM DEPARTMENT**SJR3536M****GOH SIEW CHUANG**

7 PUNGGOL FIELD WALK

#03-17

SINGAPORE 828742

CONTACT NO : 91069003

DATE	:	13-JUL-2020
MAKE	:	TOYOTA
MODEL	:	HARRIER 2.0 PREMIUM AT
		AIRBAG 2WD 5DR
CHASSIS NO	:	ZSU600073338
ENGINE NO	:	3ZRB736264
SERVICE ADVISOR	:	SHARIFAH
PAGE	:	1 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	REAR BUMPER	881.50
1	REAR BUMPER SIDE RETAINER RH	
1	REAR BUMPER SIDE RETAINER LH	
1	REAR BUMPER LOWER GARNISH	
1	REAR BUMPER SPONGE	
1	REAR END PANEL	
1	REAR END PANEL TOP GARNISH	
1	TAILGATE	
1	TAIL GATE EMBLEM	
1	TAIL GATE EMBLEM "HARRIER"	
1	TAIL GATE INNER TRIM	
1	TAIL GATE OUTER GARNISH	
1	TAIL GATE INNER LOCK	
1	TAIL GATE LOCK SENSOR	
1	REAR SMART BUZZER	
1	TAIL GATE WEATHERSTRIP	
3	REAR WINDSCREEN MOULDING	

Dis	1,601.95	✓
11	69.70	X
Ref	69.70	✓
Dis	420.69	✓
Torn	137.80	✓
11	821.30	✓
11	421.47	X
11/Ref	1,621.90	✓
11	65.80	X
11	76.85	✓
11	661.75	X
11	1,312.75	X
11	1,016.40	X
11	136.40	X
11	150.33	X
11	373.36	✓
11	225.06	✓

Sub Total**9,183.21****0.00****SPECIAL NETT**

1	REAR WINDSCREEN SEALANT	
1	REAR WINDSCREEN INNER SEAL	
1	REAR WINDSCREEN PRIMER & CLEANER	
1	REAR END PANEL SEALANT	
10	REAR END PANEL TOP GARNISH CLIPS	
10	REAR BUMPER CLIPS	
1	NUMBER PLATE W/CASING	
2	REVERSE SENSOR	

11	50.00	40
11	50.00	30
11	50.00	X
11	50.00	✓
11	50.00	X
11	50.00	✓
11	60.00	X
should	600.00	200

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000351**

TO : MS FIRST CAPITAL INSURANCE LIMITED
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 13-JUL-2020
 MAKE : TOYOTA
 MODEL : HARRIER 2.0 PREMIUM AT
 AIRBAG 2WD 5DR
 CHASSIS NO : ZSU600073338
 ENGINE NO : 3ZRB736264
 SERVICE ADVISOR : SHARIFAH
 PAGE : 2 OF 2

SJR3536M
GOH SIEW CHUANG
 7 PUNGGOL FIELD WALK
 #03-17
 SINGAPORE 828742
 CONTACT NO : 91069003

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REVERSE CAMERA	380.00	× NN
Sub Total		1,340.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,000.00	600
1	TO SPRAY PAINT ON AFFECTED AREAS	1,200.00	700
1	TO CHECK WIRING	150.00	20
1	TO APPLY UNDERCOATING FOR RUST PROOFING	150.00	60
1	TO DISMANTLE AND REPLACE REAR WINDSCREEN COMPONENTS	150.00	120
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	120.00	50
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	120.00	>
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	180.00	60
1	TO DISMANTLE, REPLACE AND/OR REPAIR TAILGATE COMPONENTS	250.00	60
Sub Total		3,320.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SUB-TOTAL 13,843.21
GST - 7 % 969.02
TOTAL 14,812.23

Acknowledged by Repairer
 Signature:
 Date:

p-4628.16
 252
 9-3471.12
 5.2-370.00
 1-1670.00
 5511.12
 207
 6408

ABWIN SERVICE PTE LTD

Prepared By