

ASS. REC. BY:

REF:

A/G/20007233/1/KC

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TR RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP / 24 HRS

9/28

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJJ 30654 Yr Regn: 09, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPV

Make: Honda Provan c.c. 1799

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 152513 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RN6 1082892

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / SRIm / STD A/RIm or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 9/7/20 D.O.I. 17/7/2020

Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/8 11:30 @ 41501 Carban

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

1) _____

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS. \$ _____

Fuel \$ _____

Others \$ _____

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761

TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg

GST:201001158E RCB NO:201001158E

SJJ3065Y
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX- 64153727
ATTN: Motor Claim Department

Not Authorized
U/Rp @ \$150.
Repair After Paint
6 days

Claim No: ESTIMATE
Estimate No: ESTIMATE
Date: 17-Jul-20
Policy No: DMPCNA00021892001
Veh Reg No: SJJ3065Y
Make/Model: HONDA STREAM 1.8X A

WS Ref: TP/AIG
Claim Type: TP CLAIM
Accident Date: 09/07/2020
TP Veh Reg No: EQ699K

Chassis No: RN61082892
Engine No: R18A1792020
Reg. Date: 08/09/2008

Page : 1 of 1

Estimate Repair Cost to Vehicle : SJJ3065Y

Description

U/Price

Quantity

Amount

List

- 1 FRT BUMPER
- 2 FRT BUMPER REINFORCEMENT
- 3 FRT BUMPER LH SIDE RETAINER
- 4 FRT BUMPER CLIPS @ 3.50/PC
- 5 FRT BUMPER LH FOG LAMP GARNISH
- 6 FRT LH FENDER
- 7 FRT LH FENDER INNER SHIELD
- 8 FRT LH FENDER INNER SHIELD CLIPS @3.50/PC
- 9 LH HEADLAMP 'HID'
- 10 LH HEADLAMP LOWER RETAINER
- 11 FRT GRILLE
- 12 FRT GRILLE CLIPS @3.50/PC
- 13 AIR FILTER RESONATOR
- 14 FRT LH FENDER INNER PANEL
- 15 BONNET

SS

Bt / CM

1 PC	793.10	✓
1 PC <i>Rn</i>	218.50	✓
1 PC <i>CM</i>	19.80	✓
6 PCS <i>Ma</i>	21.00	✓
<i>Rd</i> 1 PC	22.80	✓
1 PC <i>Rn</i>	539.20	✓
1 PC <i>CM</i>	118.90	✓
6 PCS <i>Mc</i>	21.00	✓
<i>Bn</i> 1 PC	927.10	✓
1 PC <i>CM</i>	36.50	✓
<i>m/k/m</i> 1 PC	289.10	✓
4 PCS <i>Ma</i>	14.00	✓
1 PC <i>Rd</i>	198.90	✓
<i>Bn</i> 1 PC	389.10	✓
1 PC <i>Rn</i>	638.90	✓

4247.90

Less 20%

849.58 3398.32

Labour

- 16 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, FRT GRILLE, FRT FENDERS, BONNET & ATTACHMENT, KNOCK & REPAIR FRT SUPPORT PANEL, CUT, WELD, RENEW FRT LH FENDER INNER PANEL & REALIGN THE SAME
- 17 PUTTY & RESPRAY FRT LH DOOR, FRT BUMPER, REINFORCEMENT, SUPPORT PANEL, FRT LH FENDER, FRT LH FENDER INNER PANEL, BONNET
- 18 REMOVE & REFIX FRT LH SPORT RIM, REPAIR, SPRAY AND BALANCING
- 19 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT
- 20 RUSTPROOFING

800.00 *650*

1100.00 *1000*

80.00 *60*

60.00 ✓

60.00 ✓

2100.00

TOTAL

Add GST 7%

GRAND TOTAL

5498.32

384.88

5883.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
 Owner ID: 259F

Vehicle Details

Vehicle No.: SJJ3065Y
 Vehicle to be Exported: No
 Intended Deregistration Date: 09 Jul 2020
 Vehicle Make: HONDA
 Vehicle Model: STREAM 1.8X A
 Primary Colour: Black
 Manufacturing Year: 2008
 Engine No.: R18A1792020
 Chassis No.: RN61082892
 Maximum Power Output: 103.0 kW (138 bhp)
 Open Market Value: \$17,485.00
 Original Registration Date: 08 Sep 2008
 First Registration Date: 08 Sep 2008
 Transfer Count: 2
 Actual ARF Paid: \$17,485.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 07 Sep 2028
 COE Category: B - Car (1601cc & above)
 COE Period(Years): 10
 PQP Paid: \$33,377.00
 COE Rebate Amount: \$27,242.00
Total Rebate Amount: \$27,242.00

The information contained herein is correct as at 09 Jul 2020

OK