

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: **SLQ 3705 Z**
 Model: **Kia Sorento 2.2**
 Chassis No: **KNAPH81BSH5353761**
 Year of manufacturing: **2017**

S/No	Qty	Items	Unit Price	Amount	
1	1	Front bumper / <i>cut</i>	\$ 675.80	\$ 675.80	✓
2	2	Front bumper retainer <i>CH x NN</i>	\$ 25.90	\$ 51.80	16
3	1	Front bumper towing cover <i>OH - CAA</i>	\$ 23.70	\$ 23.70	✗
4	1	Front bumper sensor <i>x NN</i>	\$ 212.50	\$ 212.50	✓
5	1	Front bumper reinforcement <i>DM</i>	\$ 587.10	\$ 587.10	✗
6	1	RHS Front bumper fog light <i>x NN</i>	\$ 594.60	\$ 594.60	✓
7	1	RHS Front bumper fog light cover <i>BR</i>	\$ 104.30	\$ 90.6	104.30 ✓
8	1	Front lower bumper <i>cut</i>	\$ 698.70	\$ 655.5	698.70 ✓
9	1	Front radiator grille <i>x NN</i>	\$ 812.50	\$ 812.50	✗
10	1	Front lower bumper grille <i>x NN</i>	\$ 164.70	\$ 164.70	✗
11	1	RHS Front fender <i>x repair</i>	\$ 478.40	\$ 478.40	✗
12	1	RHS Front fender shield <i>re.</i>	\$ 89.70	\$ 89.70	✓
13	1	RHS Front fender ARCH	\$ 104.70	\$ 104.70	✓
14	1	RHS headlamp <i>CAA</i>	\$ 2,310.50	\$ 2,310.50	2210
15	1	RHS front absorber <i>x</i>	\$	\$ -	
16	1	RHS front knuckle <i>x NN</i>	\$	\$ -	
17	1	RHS front lower arm <i>x</i>	\$	\$ -	
18	1	RHS front knuckle bearing <i>Jun</i>	\$	\$ 315.5	- 279
			4899.6	\$ 6,909.00	
			-10%	\$ 690.90	
			4409.64	Total for spare parts \$ 6,218.10	

Special Nett

1	10	Front bumper clip <i>3 ac</i>	\$ 6.00	\$ 60.00	✓
2	10	Front fender ARCH clip	\$ 6.00	\$ 60.00	✓
3	1	RHS front rim <i>cut</i>		450 1200	✓
4	1	RHS front tyre		150 950	✓
			Total for SP	\$ 120.00	
			Sub-Total for Parts :	\$ 6,338.10	

~~Sponge / CAA~~

~~support panel / CAA~~

~~Nozzle / Jun~~

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention	\$	900.00 <i>700.</i>
2		To putty and spray paint on all accident damage parts and other accident	\$	800.00 450. <i>450.</i>
3		To check wiring system to facilitate repair and refit the same	\$	50.00 <i>30.</i>
4		Apply rust proofing on the adjacent panels	\$	50.00 <i>X</i>
5		To supply under coating / putty on parts replaced	\$	50.00 <i>X</i> } <i>na</i>
6		To perform water seepage test after repair	\$	80.00 <i>X</i>
7		To remove and refit front reverse sensor	\$	80.00 <i>40.</i>
8		Reset engine management system with diagnostic fault	\$	150.00 <i>X</i> } <i>na</i>
9		To conduct headlamp focus	\$	150.00 <i>X</i> } <i>na</i>
10		To remove and refit under carriage	\$	350.00 50. <i>50.</i>
11		To reset wheel alignment	\$	150.00 <i>60.</i>
TOTAL AMOUNT :			\$	2,810.00 1330
OVERALL COST :			\$	9,148.10

7374.78

-20%: 5900

6 Days.

lumpsum repair.

After repair photos.

Gue Rian

13/7/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: SLQ 3705 Z**Model: Kia Sorento 2.2****Chassis No: KNAPH81BSH5353761****Year of manufacturing: 2017**

<u>S/No</u>	<u>Qty</u>	<u>Items</u>	<u>Unit Price</u>	<u>Amount</u>	
1	1	Fornt bumper sponge ✓ CRA	\$ 143.50	\$ 143.50	121.6
2	2	Front support panel ✓ CRA	\$ 763.70	\$ 1,527.40	760
3	1	RHS front headlamp nozzle ✓ BR	\$ 236.90	\$ 236.90	213
				<u>\$ 1,907.80</u>	1094.6
				<u>-10% \$ 190.78</u>	
		Total for spare parts		<u>\$ 1,717.02</u>	985.14