

Vehicle No: **SLQ 3705 Z**
 Model: **Kia Sorento 2.2**
 Chassis No: **KNAPH81BSH5353761**
 Year of manufacturing: **2017**

S/No	Qty	Items	Unit Price	Amount
1	1	Front bumper / <i>cut</i>	\$ 675.80	\$ 675.80
2	2	Front bumper retainer <i>CH x NN</i>	\$ 25.90	\$ 51.80
3	1	Front bumper towing cover <i>CH - CAA</i>	\$ 23.70	\$ 23.70
4	1	Front bumper sensor ? <i>x NN</i>	\$ 212.50	\$ 212.50
5	1	Front bumper reinforcement <i>x NN</i>	\$ 587.10	\$ 587.10
6	1	RHS Front bumper fog light ?	\$ 594.60	\$ 594.60
7	1	RHS Front bumper fog light cover / <i>cut</i>	\$ 104.30	\$ 104.30
8	1	Front lower bumper / <i>cut</i>	\$ 698.70	\$ 698.70
9	1	Front radiator grille <i>x GNA</i>	\$ 812.50	\$ 812.50
10	1	Front lower bumper grille <i>x</i>	\$ 164.70	\$ 164.70
11	1	RHS Front fender <i>x repair</i>	\$ 478.40	\$ 478.40
12	1	RHS Front fender shield <i>re.</i>	\$ 89.70	\$ 89.70
13	1	RHS Front fender ARCH <i>DE</i>	\$ 104.70	\$ 104.70
14	1	RHS headlamp / <i>CAA</i>	\$ 2,310.50	\$ 2,310.50
15	1	RHS front absorber <i>x</i>	\$	\$ -
16	1	RHS front knuckle <i>x GNA</i>	\$	\$ -
17	1	RHS front lower arm <i>x</i>	\$	\$ -
18	1	RHS front knuckle bearing / <i>Jun</i>	\$	\$ -
				\$ 6,909.00
				-10% \$ 690.90
Total for spare parts				\$ 6,218.10

Special Nett				
1	10	Front bumper clip / <i>3 ac</i>	\$ 6.00	\$ 60.00
2	10	Front fender ARCH clip	\$ 6.00	\$ 60.00
3	1	RHS front rim / <i>cut</i>		
4	1	RHS front tyre		
Total for SP				\$ 120.00
Sub-Total for Parts :				\$ 6,338.10

Sponge / CAA
support panel / CAA
Nozzle / Jun

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention	\$	900.00 <i>700.</i>
2		To putty and spray paint on all accident damage parts and other accident	\$	800.00 400 <i>450.</i>
3		To check wiring system to facilitate repair and refit the same	\$	50.00 <i>30.</i>
4		Apply rust proofing on the adjacent panels	\$	50.00 <i>X</i>
5		To supply under coating / putty on parts replaced	\$	50.00 <i>X</i> } <i>na</i>
6		To perform water seepage test after repair	\$	80.00 <i>X</i>
7		To remove and refit front reverse sensor	\$	80.00 <i>to.</i>
8		Reset engine management system with diagnostic fault	\$	150.00 <i>X</i> } <i>na</i>
9		To conduct headlamp focus	\$	150.00 <i>X</i> } <i>na</i>
10		To remove and refit under carriage	\$	350.00 400 <i>50.</i>
11		To reset wheel alignment	\$	150.00 <i>60.</i>

TOTAL AMOUNT : \$ 2,810.00
OVERALL COST : \$ 9,148.10

6 Days.
lumpsum repair.
After repair photos.
Gue Rian
13/7/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: