

Vehicle No: **SLQ 3705 Z**  
 Model: **Kia Sorento 2.2**  
 Chassis No: **KNAPH81BSH5353761**  
 Year of manufacturing: **2017**

S/No	Qty	Items	Unit Price	Amount
1	1	Front bumper / <i>cut</i>	\$ 675.80	\$ 675.80
2	2	Front bumper retainer <i>← LH x NN</i>	\$ 25.90	\$ 51.80
3	1	Front bumper towing cover <i>← RH - CPA</i>	\$ 23.70	\$ 23.70
4	1	Front bumper sensor <i>x NN</i>	\$ 212.50	\$ 212.50
5	1	Front bumper reinforcement <i>?</i>	\$ 587.10	\$ 587.10
6	1	RHS Front bumper fog light <i>x NN</i>	\$ 594.60	\$ 594.60
7	1	RHS Front bumper fog light cover <i>?</i>	\$ 104.30	\$ 104.30
8	1	Front lower bumper <i>cut</i>	\$ 698.70	\$ 698.70
9	1	Front radiator grille <i>x NN</i>	\$ 812.50	\$ 812.50
10	1	Front lower bumper grille <i>x NN</i>	\$ 164.70	\$ 164.70
11	1	RHS Front fender <i>x repair</i>	\$ 478.40	\$ 478.40
12	1	RHS Front fender shield <i>re.</i>	\$ 89.70	\$ 89.70
13	1	RHS Front fender ARCH	\$ 104.70	\$ 104.70
14	1	RHS headlamp <i>CPA</i>	\$ 2,310.50	\$ 2,310.50
15	1	RHS front absorber <i>x</i>	\$	\$ -
16	1	RHS front knuckle <i>x NN</i>	\$	\$ -
17	1	RHS front lower arm <i>x</i>	\$	\$ -
18	1	RHS front knuckle bearing <i>Jun</i>	\$	\$ -
				<b>\$ 6,909.00</b>
				<b>-10% \$ 690.90</b>
<b>Total for spare parts</b>				<b>\$ 6,218.10</b>

Special Nett				
1	10	Front bumper clip <i>← 3 pc</i>	\$ 6.00	\$ 60.00
2	10	Front fender ARCH clip	\$ 6.00	\$ 60.00
3	1	RHS front rim <i>← cut</i>		
4	1	RHS front tyre		
<b>Total for SP</b>				<b>\$ 120.00</b>
<b>Sub-Total for Parts :</b>				<b>\$ 6,338.10</b>

*Sponge ✓ CPA*  
*support panel ✓ CPA*  
*Nozzle ✓ Jun*

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention	\$	900.00 <i>700.</i>
2		To putty and spray paint on all accident damage parts and other accident	\$	800.00 <del>400</del> <i>450.</i>
3		To check wiring system to facilitate repair and refit the same	\$	50.00 <i>30.</i>
4		Apply rust proofing on the adjacent panels	\$	50.00 <i>X</i>
5		To supply under coating / putty on parts replaced	\$	50.00 <i>X</i> } <i>na</i>
6		To perform water seepage test after repair	\$	80.00 <i>X</i>
7		To remove and refit front reverse sensor	\$	80.00 <i>40.</i>
8		Reset engine management system with diagnostic fault	\$	150.00 <i>X</i> } <i>na</i>
9		To conduct headlamp focus	\$	150.00 <i>X</i> } <i>na</i>
10		To remove and refit under carriage	\$	350.00 <del>400</del> <i>50.</i>
11		To reset wheel alignment	\$	150.00 <i>60.</i>

TOTAL AMOUNT : \$ 2,810.00  
OVERALL COST: \$ 9,148.10

*6 Days.*  
*lumpsum repair.*  
*After repair photos.*  
*Gue Rianp*  
*13/7/2020.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: