



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2106884

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 05/10/2021
Reference CC4/FCI20007237/Upa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FP 4365R
Insured Veh. SH 7950U
Claim No. D20002531MFSH/1
Policy No. D-20094922MFSH
Accident Date 22/06/2020
Inspection Date 14/07/2020

Description	Total
Survey Inspection	309.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	309.00
GST (7%)	21.63
Grand Total	330.63

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20007237/Upa3q2	
			Date: 05/10/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7950U	Veh. Inspected	FP 4365R	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20002531MFSH/1	Excess (\$)	0.00	
Assign From	VIC	Assign Date	13/07/2020	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA DT200WR	c.c	199	
Engine No.	HIDDEN	Year of Reg.	1997	
Chassis No.	3XP064154	Colour	WHITE	
Odometer	32549 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	3.00-21	DUNLOP	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	4.00-18	DUNLOP	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/06/2020	Inspection Date	14/07/2020	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FP 4365R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE -BAR	BENT	220.00	195.00
1	CLUTCH LEVER	SCRATCHED	95.00	95.00
1	HANDLE GRIP LH	TORN	40.00	40.00
1	MIRROR LH	BROKEN	45.00	45.00
1	FRONT SIGNAL -L/H	BROKEN	110.00	98.00
1	FRONT FENDER	WARPED	230.00	230.00
1	GEAR PEDAL	BENT	95.00	95.00
2	RIDER FOOTREST	NOT NECESSARY	110.00	-
1	REAR FENDER	TO REPAIR SEE LABOUR	135.00	-
1	REAR SIGNAL -L/H	CUT	110.00	98.00
1	FRONT FAIRING	TO REPAIR SEE LABOUR	160.00	-
1	SIDE STAND	TO REPAIR SEE LABOUR	120.00	-
1	FORK OUTER COVER -L/H	CUT	95.00	95.00
	LESS 10% DISCOUNT		-156.50	-99.10
			1,408.50	891.90
2	FRONT FORK ASSY (LOCAL PURCHASE) (SN)	BENT	3,600.00	80.00
	LESS 10% DISCOUNT		-360.00	-
			3,240.00	80.00
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	FRT NECESSARY / REAR BROKEN	28.00	20.00
1	HELMET (SN)	CUT	180.00	60.00
1	SET STICKER (SN)	NECESSARY	480.00	280.00
1	BEARING CONE (SN)	NOT NECESSARY	120.00	-
			808.00	360.00
<u>LABOUR</u>				
	TO PROVIDE TOWING SERVICE.		50.00	35.00

Report Ref No. CC4/FCI20007237/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF REAR FENDER ,FRONT FAIRING AND SIDE STAND.		380.00	280.00
			430.00	315.00
GRAND TOTAL			5,886.50	1,646.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CC4/FCI20007237/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FP 4365R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FP 4365R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

