

ARC Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2007-088
DATE : 9-Jul-2020
POLICY NO. : FWD PNPV2020-00005998
VEHICLE REG. NO. : SML4183L
VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A) S

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Bumper / CRU.	1	\$ 500.00	\$ 500.00
2	Front Bumper Clip / NRC	10	\$ 3.00	\$ 30.00
3	Front Bumper Retainer LH / CRU	1	\$ 30.00	\$ 30.00
4	Front Bumper Upper Support Bracket LH - 86554B	1	\$ 30.00	\$ 30.00
5	Front Bumper Side Grille LH - 86512L / CRU.	1	\$ 50.00	\$ 50.00
6	Front Bumper Lower Moulding LH - 86571P / CUT.	1	\$ 50.00	\$ 50.00
7	Front Bumper Fog lamp LH - 92302A / CRA	1	\$ 200.00	\$ 200.00
8	Front Air Curtain Duct LH - 86567E X SVC	1	\$ 30.00	\$ 30.00
9	Front Bumper Under Lip Assy - 86590E / CHA	1	\$ 90.00	\$ 90.00
10	Front Bumper Under Cover X SVC	1	\$ 150.00	\$ 150.00
11	Front Bumper Under Cover Clip X SVC	10	\$ 3.00	\$ 30.00
12	Front Reinforcement X SVC	1	\$ 700.00	\$ 700.00
13	Front Sponge/absorber X SVC	1	\$ 120.00	\$ 120.00
14	Front Grille Assy ?	1	\$ 480.00	\$ 480.00
15	Front Headlamp LH / CRU.	1	\$ 1,800.00	\$ 1,800.00
16	Front Headlamp Bracket LH / CRA	1	\$ 30.00	\$ 30.00
17	Front Fender LH / CRU	1	\$ 980.00	\$ 980.00
18	Front Fender Shield LH / CRU	1	\$ 90.00	\$ 90.00
19	Front Fender Clip / NRC	10	\$ 3.00	\$ 30.00
20	Support Panel X ?	1	\$ 980.00	\$ 980.00
21	Front Buzzer Assy / SCR.	1	\$ 80.00	\$ 80.00
22	Front Knuckle LH ?	1	\$ 380.00	\$ 380.00
23	Front Bearing & Wheel Hub LH ?	1	\$ 120.00	\$ 120.00
24	Front Tie Rod LH ?	1	\$ 120.00	\$ 120.00
25	Front Tie Rod End LH ?	1	\$ 100.00	\$ 100.00
26	Front Absorber LH ?	1	\$ 300.00	\$ 300.00
27	Front Lower Arm LH ?	1	\$ 300.00	\$ 300.00
28	Front Stabiliser ?	1	\$ 220.00	\$ 220.00
29	Front Stabiliser Linkage LH ?	1	\$ 80.00	\$ 80.00
30	Hyundai Rim R16 / SCR	1	\$ 900.00	\$ 900.00
31	Front Bonnet / DN	1	\$ 1,980.00	\$ 1,980.00

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2007-088

DATE : 9-Jul-2020

POLICY NO. : FWD PNPV2020-00005998

VEHICLE REG. NO. : SML4183L

VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A) S

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
32	Front Bonnet Insulator Clip ✕	10	\$ 3.00	\$ 30.00
33	Front Bonnet Rubber Seal ✕	1	\$ 50.00	\$ 50.00
34	Duct Assy Extension - 28220E ?	1	\$ 220.00	\$ 220.00
Total Spare Parts				\$ 11,280.00
SPECIAL NETT				
35	Front Tire LH (205 55 R16) ✕	1	\$ 180.00	\$ 180.00
36	Coolant Fluid 4 Litre ✕	1	\$ 30.00	\$ 30.00
Total Special Nett				\$ 210.00
LABOUR				
37	Spray Painting Front Bonnet, Bumper, Fender LH & Doors LH	1	\$ 1,000.00	\$ 1,000.00
38	Repair, Replace and Refill Affected Accident Area Incl. Wheelhse	1	\$ 1,000.00	\$ 1,000.00
39	Remove and Replace Front Undercarriage	1	\$ 300.00	\$ 300.00
40	Wheels Computer Alignment / Wheel Balancing	1	\$ 80.00	\$ 80.00
41	Remove, Refit A/C Condenser, Radiator & Refill A/C Gas	1	\$ 100.00	\$ 100.00
42	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,510.00
Amount Before Excess				\$ 14,000.00
Add GST @ 7%				980.00
Total Amount Payable				\$ 14,980.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Repair day - 5 days.

p/p.

before paint photo.

Sum Pin (Lkk)

13/07/2020.

TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: