



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 19400367W
GST Reg No. MR 8506111-X

ESTIMATE FOR SGR686T

Tan Boon Kiat Daniel (chen Wen)

56 Lakeside Drive
#16-32
Singapore 648318

Mobile: +6592261236

Vehicle & Document Information

WIP No 43661
Reg No/Reg Date SGR686T / 01/02/2017
Date In/Mileage
Chassis No WDD2050402R243661
Engine No 27491030821326
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	27/07/2020/ 08:24	YK	395 / Yik Chan Hoe
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

2 REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE :G300246092 // 10/07/2020				
DRIVE IN/EXCESS : 13/07/2020 // TP VEH NO SLG619L LONPAC				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
S BPNSUB				
1 PC FRONT NO PLATE				
A BPILAB				
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLAC WITH NEW				
BODY PANELS WITH REFINISH				
A BPIRES				
RESPRAY BONNET, FRONT BUMPER AND LEFT FRONT FENDER.				
A BPILAB				
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO				
STANDARD SETTINGS. NETT				
A BPILAB				
CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT				
A BPILAB				
INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT				
M LEFT HEADLAMP UNIT				
M FRONT BUMPER				
M LEFT FRONT BASIC MOUNTING FOR BUMPER				
M FRONT IMPACT ABSORBER				
M FRONT TOP BASIC MOUNTING FOR BUMPER				
M FRONT LICENSE PLATE MOLDING				
M BONNET				
M RADIATOR GRILLE				

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

Confirmed & accepted by:

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Supplementary item(s) must be resurveyed and

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Nett 13,479.51
7% GST on 13479.51 943.57
Total Payable 14,423.08



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg