



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGR686T

Tan Boon Kiat Daniel (chen Wen

56 Lakeside Drive  
#16-32  
Singapore 648318

Mobile: +6592261236

### Vehicle & Document Information

WIP No	<b>43661</b>
Reg No/Reg Date	<b>SGR686T / 01/02/2017</b>
Date In/Mileage	<b>0</b>
Chassis No	<b>WDD2050402R243661</b>
Engine No	<b>27491030821326</b>
Make/Model	<b>MB/MB C 180 SEDAN (W205) "AVANTGARDE / A</b>
Colour/Trim	<b>021 197 Obsidian Bl/ 041 101 ARTICO Blac</b>

Account No	Terms	Date/Time Printed	CSE	Operator			
CSM00128	Cash	13/07/2020/ 10:28	YK	395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

### Z REQUEST

Customer Request  
M BPNSUN

POLICY NO/ACC DATE :G300246092 // 10/07/2020  
DRIVE IN/EXCESS : 13/07/2020 // TP VEH NO SLG619L LONPAC  
DATE IN/DATE SURVEY:  
BY/AUTHORIZED ON :

### S BPNSUB

1 PC FRONT NO PLATE

### A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW  
BODY PANELS WITH REFINISH

### A BPIRES

RESPRAY BONNET, FRONT BUMPER AND LEFT FRONT FENDER.

### A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO  
STANDARD SETTINGS. NETT

### A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT

### M LEFT HEADLAMP UNIT

1.00 3280.44 00.00 3280.44

### M FRONT BUMPER

1.00 1580.69 00.00 1580.69

### M LEFT FRONT BASIC MOUNTING FOR BUMPER

1.00 83.81 00.00 83.81

### M FRONT IMPACT ABSORBER

1.00 164.30 00.00 164.30

### M FRONT TOP BASIC MOUNTING FOR BUMPER

1.00 89.03 00.00 89.03

### M FRONT LICENSE PLATE MOLDING

1.00 130.49 00.00 130.49

### M BONNET

1.00 2114.35 00.00 2114.35

### M RADIATOR GRILLE

1.00 136.40 00.00 136.40

### Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 12,939.51  
7% GST on 12939.51 905.77

Authorized signatory and company stamp

Total Payable 13,845.28

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany