

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 9-Jul-20

MODEL: TOYOTA PRIUS

INSURANCE: AIG

VEHICLE NO.: SH8871H

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
BONNET <i>kt</i>	1	\$950.50	\$950.50	
INSULATOR, HOOD <i>HH</i>	1	\$398.10	\$398.10	X
INSULATOR CLIPS <i>HH</i>	1	\$3.60	\$3.60	X
BONNET RUBBER <i>HH</i>	1	\$35.50	\$35.50	X
BONNET CABLE <i>HH</i>	1	\$83.20	\$83.20	X
BONNET HINGE (RH) <i>kt</i>	1	\$87.70	\$87.70	X
FRONT BUMPER COVER <i>HH</i>	1	\$499.90	\$499.90	X
LAMP ASSY, FOG, RH <i>Scratched / mainly broken</i>	1	\$920.00	\$920.00	X
FRONT BUMPER CLIPS <i>HH</i>	1	\$22.00	\$22.00	X
FRONT BUMPER SIDE RETAINER <i>o/s broken</i>	1	\$77.00	\$77.00	X
FRONT LOWER CROSSMEMBER <i>HH</i>	1	\$357.70	\$357.70	X
FRONT UNDER COVER <i>HH</i>	1	\$180.80	\$180.80	X
FRONT BUMPER TOP GARNISH <i>HH</i>	1	\$225.40	\$225.40	X
COVER, FRONT BUMPER HOLE, RH <i>HH</i>	1	\$28.38	\$28.38	X
ABSORBER, FRONT BUMPER, LOWER <i>HH</i>	1	\$127.70	\$127.70	X
RADIATOR ASSY <i>HH</i>	1	\$1,841.80	\$1,841.80	X
COOLANT <i>HH</i>	1	\$45.00	\$45.00	X
CONDENSER ASSY, W/RECEIVER <i>HH</i>	1	\$1,336.60	\$1,336.60	X
WIRING FRONT <i>HH</i>	1	\$8,450.50	\$8,450.50	X
UNIT ASSY, HEADLAMP, RH (LED) <i>broken mainly</i>	1	\$3,455.00	\$3,455.00	X
HEADLAMP ECU <i>HH</i>	1	\$682.60	\$682.60	X
HEAD LAMP PANEL (RH) <i>kt</i>	1	\$240.10	\$240.10	X
TOP PANEL SIDE <i>kt</i>	1	\$145.90	\$145.90	X
RADIATOR SPARE TANK HYBRID <i>HH</i>	1	\$125.80	\$125.80	X
WIPER SPARE TANK ASSY <i>det/mud / broken</i>	1	\$486.70	\$486.70	X
WIPER TANK NECK <i>HH</i>	1	\$89.40	\$89.40	X
FENDER SUB-ASSY, FRONT RH <i>Det/mud</i>	1	\$945.30	\$945.30	X
FRONT FENDER SHIELD <i>kt</i>	1	\$198.50	\$198.50	X
FRONT FENDER SHIELD CLIP <i>HH</i>	1	\$14.90	\$14.90	X
FRONT FENDER HYBRID EMBLEM, RH <i>HH</i>	1	\$86.50	\$86.50	X
FRONT WHEEL RIM <i>kt</i>	1	\$1,570.55	\$1,570.55	X
FRONT WHEEL HUB CAP <i>HH</i>	1	\$175.80	\$175.80	X
FRONT WHEEL HUB BEARING <i>2 Distorted</i>	1	\$559.94	\$559.94	X
FRONT SUSPENSION LOWER ARM (RH) <i>2 Distorted</i>	1	\$631.90	\$631.90	X
FRONT SHOCK ABSORBER (RH) <i>2 Distorted</i>	1	\$398.20	\$398.20	X
ABSORBER TOP MOUNTING <i>HH</i>	1	\$196.20	\$196.20	X
RACK & PINION ASSY <i>HH</i>	1	\$1,621.30	\$1,621.30	X
BAR, STABILIZER <i>HH</i>	1	\$352.40	\$352.40	X
KNUCKLE, STEERING, RH <i>2 Distorted</i>	1	\$580.80	\$580.80	X
JOINT ASSY, LOWER BALL, FRONT (RH) <i>HH</i>	1	\$199.98	\$199.98	X
DISC, FRONT <i>HH</i>	1	\$420.67	\$420.67	X

END SUB-ASSY, TIE ROD, RH <i>2 H4</i>	1	\$159.30	\$159.30	X	
SENSOR, SPEED, FRONT RH <i>2 H4</i>	1	\$446.50	\$446.50	X	
SUB TOTAL					
LESS 20% <i>25%</i>			\$29,455.62		
DISCOUNTED TOTAL			\$5,891.12		
			\$23,564.50		
FRONT TYRE (RH) <i>SVC</i>	SN	1	\$216.00	\$216.00	X
SUB TOTAL					
			\$216.00		
Labour Charge					
Panel Beating					
Spray Painting Charge	1	\$1,600.00	\$1,600.00	800/-	
Wiring Charge	1	\$1,200.00	\$1,200.00	600/-	
Tuff Kote	1	\$140.00	\$140.00	30/-	
Towing Charge	1	\$120.00	\$120.00	40/-	
Four Wheel Alignment	1	\$80.00	\$80.00	40/-	
Remove/Refix Undercarriage (Frt)	1	\$120.00	\$120.00	60/-	
Re-set Frt ABS System	1	\$400.00	\$400.00	150/-	
Remove/Refix Radiator	1	\$200.00	\$200.00	40/-	
Remove/Refix Aircon & Refill Gas	1	\$90.00	\$90.00	40/-	
Remove/Refix Dashboard	1	\$130.00	\$130.00	40/-	
Diagnostic & Resetting To Erase Fault Code	1	\$350.00	\$350.00	40/-	
	1	\$550.00	\$550.00	150/-	
TOTAL LABOUR					
			\$4,980.00		
ESTIMATE TOTAL					
			\$28,760.50		
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

13/07/2020 @ 1715hrs
 Not Antenna
 L/S *8* days
 Ryan
 2 Kk Ando
 Photo with damage
 Parts after repair.

10573.49
 SPP 3542.70
 P/P 14116.19

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 14-Jul-20

MODEL: TOYOTA PRIUS

INSURANCE: AIG

VEHICLE NO.: SH8871H (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
FRONT BUMPER REINFORCEMENT <i>st</i>	1	\$696.40	\$696.40
UNIT ASSY, HEADLAMP, LH (LED) <i>mounting broken</i>	1	\$3,455.00	\$3,455.00
RADIATOR SPARE TANK <i>broken mounting</i>	1	\$385.80	\$385.80
FRONT WINDSCREEN SIDE GARNISH <i>dislodged</i>	1	\$186.40	\$186.40
SUB TOTAL			
LESS 20% <i>25%</i>			\$4,723.60
DISCOUNTED TOTAL			\$944.72
			\$3,778.88

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

yan
2kk Auto
[Signature]

3542.70