

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC4/PC120007268/UK53

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SML 4966U

at Workshop m/s

ASIC motor sport

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

£8k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

10

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 27867

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SML 4966U

Yr Regn:

5/19

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Monde Fiat

c.c

1317

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

23858

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK3 1348564

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

13/7/20

D.O.I.

14/7/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

** Note new parts replacement*

5/8/20 Repair sum £ 6500 confirmed with AAH long

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

LUK: khanchua

Not Authorized

14/7/20

Page No. 1

7 days

VEHICLE NO. SML 4966U

HONDA FIT

Repair sum 6500

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Tail Gate 749.60	Body	1425.00	—
2	Tail Gate Number Plate lamps @ \$75.00	REFIX	11 0.00	X
1	Tail Gate Inner Lock 197.40	Tw/ym	286.50	—
1	Tail Gate Inner lock catch	11	42.00	X
1	Tail Gate 3rd brake light	REFIX	11 0.00	X
2	RHS & LHS Tail Gate reflectors @472.50	86.50 n/s	scr 945.00	1pc
1	Tail Gate Wiper Motor	11	342.00	X
1	Tail Gate Wiper Blade	REFIX	11 0.00	X
2	Tail Gate Damper @ \$246.00	11	492.00	X
2	Tail Gate top hinges @62.50	11	125.00	X
2	Tail Gate rubber stopper @18.00	11	36.00	X
1	Tail Gate inner handle 48.60	De	98.00	—
1	Rear boot edge Weatherstrip 145.60	Tw/	262.70	—
1	Tail Gate centre (outer) Garnish	cut/	CNG 284.00	—
1	Tail Gate Emblem - FIT	rec	52.00	—
1	Tail Gate (Honda)centre badge 38.00	rec	48.00	—
1	Tail Gate Inner Trim Board 241.20	De/	To. n 324.00	—
1	Rear Windscreen moulding 68.10	rec	142.00	—
1	Rear Windscreen Moulding (lower)	rec	68.00	—
2	Tail Lamp LH & RH @875.40 288.20x2=	576.40	scr/cne 1750.80	—
1	Rear Floor Panel Top Board 386	warped	392.00	—
1	Rear Floor Panel	R	982.00	X
1	Rear Floor Panel tool tray (foam)	De	298.00	—
1	Rear End Panel 328.60	Body	785.00	—
1	Rear End Panel Top Garnish 112.80	Tw/	242.00	—
1	Top Roof Panel *Paint	REPAIR/LABOUR*	R 0.00	X
1	Rear Bumper 492.70	D. S	1124.00	—
2	Rear Bumper corner garnish @122.00 65	n/s	cne 244.00	1pc
1	Rear Bumper centre garnish strip	D. S	72.00	—
2	Rear Bumper Side Retainer @ \$58.10 25x2=	50	But 116.20	—
2	Rear fenders RHS & LHS @745.00	R	1490.00	X
2	Rear Fender Inner splash Shields @125.00	11	250.00	X
2	Rear Fender inner side trim RH & LH @298.50	n/s	De 597.00	1pc
1	Rear exhaust silencer assembly	R	782.00	X
2	Rear exhaust mountings	11	48.00	X
			14145.20	
		less 20%	2829.04	20%
			11316.16	
		PARTS C/F	11316.16	

4659

202

3727.2

VEHICLE NO. SML 4966U

HONDA FIT

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>	PARTS B/F	11316.16	
	<u>SPECIAL NETT ITEMS</u>			
1set	Rear bumper clips	new	60.00	35
1set	Rear fender inner splash shield clips	new	80.00	X
1set	Tail Gate inner trim board clips	new	80.00	35
1	Rear end panel sealant	new	100.00	50
1	Rear floor panel insulators	new	100.00	✓
1	Rear windscreen sealant	new	120.00	40
104	Reverse sensors	shocked	280.00	200
1	Rear buzzer	one	380.00	120
1	Rear antenna sensor	one	150.00	✓
2	RHS & LHS Rear fender 1/4 glass sealant	new	120.00	X
	TOTAL PARTS		12636.16	

730

VEHICLE NO. SML 4966U HONDA FIT

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the REAR affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	2000.00	1100
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (roof panel)	2000.00	1280
3	To remove and refix Rear RH & LH fender glass	180.00	11 X
4	To remove and replace reverse sensors and check for proper function	100.00	50
5	To remove and replace reverse camera and check for proper function	100.00	
6	To remove and refix Rear windscreen video cam and check for proper function	100.00	✓
7	To remove and refix fittings, inner trims, garnish etc. to facilitate repairs at rear	250.00	80
8	To provide anti rust treatment on affected areas	240.00	80
9	To remove ,refix & check wiring system for proper function	150.00	20
10	To remove and refix rear windscreen	140.00	Replaced X
11	To remove and replace rear exhaust silencer assembly realign to fit and check for proper system function	250.00	60
Labour Total :		5510.00	
TOTAL (PARTS & LABOUR):		18146.16	2770

NOTE: The parts listed in this PRELIMINARY ESTIMATE will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 3727.20
S.W - 730.00
L - 2770.00
7227.20
102
6504