

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A1620007272/UKS3

ASSIGNMENT

From:

Date:

Veh No: FBK 1799R Yr Regn: 4/15

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

FBK 1799R

Make: Yamaha VBR c.c 124

at Workshop m/s

BH/H

Colour: Red/Black A/C: Insured / Std / NI / NA

of

Sp. Reading: 61725 T/Radio: Insured / Std / NI / NA

Insured:

SK 2201C

Eng/No:

Policy No.

C/No: LBPRE 10100005-3740

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or affected

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Brim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

SK

Tyre Size: F: 2.75-18

R: 3.00-18

IDAC Accident Report:

Consistent? : Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

metzeler

GIA / PR Seen:

Consistent? : Yes or No

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

10/17/20

D.O.I.

14/7/20

Lum Sum:

%

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

24H

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA62277 RT4 2723

B1 involved

3/8/20 confirmed L/S \$1750 with Raymond

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$)

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 36344

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 11/07/2020
CLAIM NO. : 11578
POLICY NO. : MC/00780777

FROM : HASRIANAH

VEHICLE NO. : FBK1799R
MAKE/MODEL : YAM / YBR125

Not Authorised
2hr
2/5 \$1750
3 days
Telephone After
18pm
14/7/20

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 45301	Replace	1.00	\$48.00	8u 48.00 <i>x</i>
2	BRACKET MUDGUARD FRONT P/N: 46221	REPLACE	1.00	\$24.00	sent 24.00
3	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	sent 180.00
4	CRASH BAR P/N: 35878	REPLACE	1.00	\$203.00	sent 203.00
5	FORK FRONT ASSY LH P/N: 56248	REPLACE	1.00	\$625.00	sent 625.00
6	FORK FRONT ASSY RH P/N: 53204	REPLACE	1.00	\$625.00	sent 625.00
7	HEADLAMP ASSY P/N: 43129	REPLACE	1.00	\$147.00	one 147.00
8	LABOUR P/N: 06766	Supply/Install <i>✱</i>	6.00	\$63.00	300 378.00
9	LAMP SIGNAL FRONT LH P/N: 43433	REPLACE	1.00	\$21.00	one 21.00
10	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00	one 35.00
11	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00	one 35.00 <i>x</i>
12	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$97.00	one 97.00
13	STAY HEADLAMP P/N: 45750	REPLACE	1.00	\$68.00	sent 68.00

*36344 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2012-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00	111 66.00
15	TRANSPORT CHARGES P/N: 07169	✓	1.00	\$56.00	35 56.00
SUB TOTAL					\$2,608.00
GST @ 7 %					\$182.56
GRAND TOTAL (SGD)					\$2,790.56

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

p-2091
 112
 1481.90
 2216.90
 22
 1773.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*36344 *

bizSAFE₃



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197002288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 36344

- Rev. 2

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

DATE : 11/07/2020
CLAIM NO. : 11578
POLICY NO. : MC/00780777

FROM : HASRIANAH

VEHICLE NO. : FBK1799R
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRACKET MUDGUARD FRONT P/N: 46221	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
2	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00 Disc %: 10.00	162.00
3	CRASH BAR P/N: 35878	REPLACE	1.00	\$203.00 Disc %: 10.00	182.70
4	FORK FRONT ASSY LH P/N: 56248	REPLACE	1.00	\$625.00 Disc %: 10.00	562.50
5	FORK FRONT ASSY RH P/N: 53204	REPLACE	1.00	\$625.00 Disc %: 10.00	562.50
6	HEADLAMP ASSY P/N: 43129	REPLACE	1.00	\$147.00 Disc %: 10.00	132.30
7	LABOUR P/N: 06766	Supply/Install	1.00	\$300.00	300.00
8	LAMP SIGNAL FRONT LH P/N: 43433	REPLACE	1.00	\$21.00 Disc %: 10.00	18.90
9	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
10	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$97.00 Disc %: 10.00	87.30
11	STAY HEADLAMP P/N: 45750	REPLACE	1.00	\$68.00 Disc %: 10.00	61.20
12	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00 Disc %: 10.00	59.40
13	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00

SUB TOTAL
GST @ 7 %

\$2,216.90
\$155.19

*36344 *

biSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363
ISO 9001: 2015