



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 36344

DATE : 11/07/2020
CLAIM NO. : 11578
POLICY NO. : MC/00780777

FROM : HASRIANAH

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

VEHICLE NO. : FBK1799R
MAKE/MODEL : YAM / YBR125

Not Authorised
2hr
2/5#
3days
Whole After
18/7/20
14/7/20

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 45301	Replace	1.00	\$48.00	8u 48.00
2	BRACKET MUDGUARD FRONT P/N: 46221	REPLACE	1.00	\$24.00	sent 24.00
3	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	sent 180.00
4	CRASH BAR P/N: 35878	REPLACE	1.00	\$203.00	sent 203.00
5	FORK FRONT ASSY LH P/N: 56248	REPLACE	1.00	\$625.00	sent 625.00
6	FORK FRONT ASSY RH P/N: 53204	REPLACE	1.00	\$625.00	sent 625.00
7	HEADLAMP ASSY P/N: 43129	REPLACE	1.00	\$147.00	one 147.00
8	LABOUR P/N: 06766	Supply/Install	6.00	\$63.00	300 378.00
9	LAMP SIGNAL FRONT LH P/N: 43433	REPLACE	1.00	\$21.00	one 21.00
10	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00	one 35.00
11	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00	sent 35.00
12	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$97.00	one 97.00
13	STAY HEADLAMP P/N: 45750	REPLACE	1.00	\$68.00	sent 68.00

*36344 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-140383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00	66.00
15	TRANSPORT CHARGES P/N: 07169	✓	1.00	\$56.00	56.00

SUB TOTAL

\$2,608.00

GST @ 7 %

\$182.56

GRAND TOTAL (SGD)

\$2,790.56

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*36344 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001:2015