

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 14-Jul-20

INSURANCE: AIG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC7767P

Description	Qty	List Price	Amount	
Boot Lid <i>dent</i>	1	\$ 2,480.40	\$ 2,480.40	✓
Boot Lid Rubber <i>damaged</i>	1	\$ 187.40	\$ 187.40	✓
Boot Lid Hinge (LH/RH) <i>HN</i>	2	\$ 71.30	\$ 142.60	X
Boot Lid Absorber (LH/RH) <i>HN</i>	2	\$ 86.70	\$ 173.40	X
Boot Lid Lock Upper <i>Dent</i>	1	\$ 224.00	\$ 224.00	✓
Boot Lid 'H' Emblem <i>Nec</i>	1	\$ 28.00	\$ 28.00	✓
Emblem-Hybrid <i>Nec</i>	1	\$ 24.30	\$ 24.30	✓
Emblem-Ioniq <i>Nec</i>	1	\$ 31.30	\$ 31.30	✓
Boot Lid Lamp(RH) <i>mainly broken</i>	1	\$ 794.40	\$ 794.40	✓
Boot Lid Trimboard <i>HN</i>	1	\$ 259.70	\$ 259.70	X
Boot Lid Trimboard Clips (10pcs) <i>HN</i>	1	\$ 11.00	\$ 11.00	X
Boot Lid Trimboard, Centre <i>HN</i>	1	\$ 159.60	\$ 159.60	X
Boot Lid Trimboard SIDE (LH/RH) <i>HN</i>	2	\$ 92.50	\$ 185.00	X
Boot Lid Trimboard REAR <i>HN</i>	1	\$ 124.80	\$ 124.80	X
Boot Lid Glass Lower Moulding <i>HN</i>	1	\$ 145.20	\$ 145.20	X
Rear Bumper <i>Dent / distorted</i>	1	\$ 459.40	\$ 459.40	✓
Rear Bumper Reinforcement <i>broken</i>	1	\$ 394.80	\$ 394.80	✓
Rear Bumper Reinforcement Bracket (LH/RH) <i>o/s Bt H/S HN</i>	2	\$ 188.10	\$ 376.20	✓
Rear Bumper Centre Moulding Assy <i>distorted / cut</i>	1	\$ 451.25	\$ 451.25	✓
Rear Bumper Lower Centre Moulding Assy <i>Bt / mainly broken</i>	1	\$ 47.50	\$ 47.50	✓
Rear Bumper Stay <i>HN</i>	1	\$ 138.10	\$ 138.10	X
Rear Bumper Side retainer (LH/RH) <i>SWC</i>	2	\$ 85.80	\$ 171.60	X
Rear Bumper Cover Clips <i>Nec</i>	1	\$ 22.00	\$ 22.00	✓
Rear Bumper Under Centre <i>Bt / damaged</i>	1	\$ 123.85	\$ 123.85	✓
Rear Bumper Side Under (LH/RH) <i>o/s broken H/S HN</i>	2	\$ 123.10	\$ 246.20	✓
Rear Bumper Rear Hook <i>HN</i>	1	\$ 94.60	\$ 94.60	X
Rear Bumper Reflector Lamp (LH/RH) <i>HN</i>	2	\$ 82.90	\$ 165.80	X
Rear Bumper Towing Cover <i>HN</i>	1	\$ 98.80	\$ 98.80	X
Licence Lamp (LH/RH) <i>HN</i>	2	\$ 85.30	\$ 170.60	X
Licence Lamp WIRE <i>HN</i>	1	\$ 135.80	\$ 135.80	X
Tail Lamp (RH) <i>mainly broken</i>	1	\$ 870.40	\$ 870.40	✓
Tail Lamp Quarter Panel (RH) <i>HN</i>	1	\$ 208.90	\$ 208.90	X
Rear Panel <i>Dent</i>	1	\$ 532.00	\$ 532.00	✓
Rear Panel Garnish <i>damaged</i>	1	\$ 346.80	\$ 346.80	✓
Spare Tyre Holder <i>HN</i>	1	\$ 223.10	\$ 223.10	X
Spare Wheel Lock Nut <i>HN</i>	1	\$ 89.50	\$ 89.50	X
Spare Tyre Panel <i>Dent</i>	1	\$ 892.50	\$ 892.50	✓
Member Assy-Rear Floor Centre <i>HN</i>	1	\$ 863.50	\$ 863.50	X
Panel Assy-Rear Floor Side (LH/RH) <i>HN</i>	2	\$ 39.40	\$ 78.80	X
Rear tray tools box RH <i>broken</i>	1	\$ 675.30	\$ 675.30	✓
Rear tray tools box LH <i>damaged</i>	1	\$ 693.20	\$ 693.20	✓
REAR TRAY LUGGS CENTER <i>mainly damaged / broken</i>	1	\$ 354.20	\$ 354.20	✓

Exhaust Pipe Insulator <i>HH</i>		1	\$ 235.00	\$ 235.00	X
Exhaust Silencer <i>Down 1 Bt</i>		1	\$ 943.50	\$ 943.50	✓
Exhaust Pipe Hanger <i>HH</i>		1	\$ 29.20	\$ 29.20	X
SUB TOTAL				\$ 15,103.50	
LESS 20%				\$ 3,020.70	
DISCOUNTED TOTAL				\$ 12,082.80	
Boot Lid City Cab Logo & Tel No Sticker <i>Hec</i>	SN	1	\$ 35.00	\$ 35.00	✓
Rear No. Plate + Trim Cover <i>Check</i>	SN	1	\$ 45.00	\$ 45.00	✓
Rear Windscreen Sealant <i>Hec</i>	SN	1	\$ 46.00	\$ 46.00	✓
Rear Bumper Rubber Mat <i>Hec</i>	SN	1	\$ 50.00	\$ 50.00	✓
Rear Bumper Reverse Sensor <i>Down</i>	SN	1	\$ 180.00	\$ 180.00	✓
SPARE TYRE PANEL TOP COVER SILICON <i>HH</i>	SN	1	\$ 250.00	\$ 250.00	X
SUB TOTAL				\$ 606.00	
Labour Charge					
Panel Beating		1	\$1,200.00	\$1,200.00	700/-
Spray Painting Charge		1	\$1,000.00	\$1,000.00	700/-
Wiring Charge		1	\$140.00	\$140.00	30/-
Tuff Kote		1	\$140.00	\$140.00	40/-
Towing Charge		1	\$80.00	\$80.00	HH
Remove/Refix Rear Windscreen Glass		1	\$120.00	\$120.00	80/-
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00	40/-
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	60/-
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	HH
TOTAL LABOUR				\$3,430.00	
ESTIMATE TOTAL				\$ 16,118.80	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

14/07/2020 @ 17:00hrs

Not Approved
Part by Part

1 year

5 days.

LKK Auto

Photo after
repair with
damaged
parts.

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: