



CAS GARAGE PTE LTD

(Reg No: 201828067/M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: 78, SHENTON WAY, #07-16
S(079120)

Khanchana

Telephone: 64193000 Fax: 68357416

Email: assignments@lkkauto.com

Make/ Model : HONDA STREAM

Date: 15.07.2020

Chassis No : JHMRN68408S204332

Vehicle No: SJJ1775U

Date/Time of Accide 11.07.2020/ 1130

Reg date : 03.09.2008

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BONNET STOPPER <i>3pk</i>	2	\$ 30.00		\$ <i>+</i> 60.00
2	FRONT BONNET INNER LOCK <i>1pk</i>	1	\$ 185.20		\$ <i>+</i> 185.20
3	FRONT BUMPER SIDE RETAINER RH <i>new</i>	1	\$ 45.80		\$ <i>✓</i> 45.80
6	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 357.60		\$ <i>+</i> 357.60
7	FRONT HEADLAMPS(HID) RH <i>lit</i>	1	\$ 1,437.00	774.60	\$ <i>1,437.00</i>
8	FRONT HEADLAMPS LOWER BRACKET RH <i>new</i>	1	\$ 79.80		\$ <i>+</i> 79.80
9	FRONT ENGINE UNDERCOVER <i>new</i>	1	\$ 159.60		\$ <i>+</i> 159.60
10	FRONT FENDER RH <i>Detel</i>	1	\$ 497.50		\$ <i>✓</i> 497.50
11	FRONT FENDER SIGNAL LAMP RH <i>new</i>	1	\$ 58.90		\$ <i>+</i> 58.90
12	FRONT FENDER TOP GARNISH RH <i>new</i>	1	\$ 98.70		\$ <i>+</i> 98.70
13	FRONT FENDER INNER COWLING RH <i>Detel</i>	1	\$ 157.90		\$ <i>✓</i> 157.90
14	FRONT FENDER SUPPRESOR GARNISH RH <i>new</i>	1	\$ 68.70		\$ <i>+</i> 68.70
15	FRONT DOOR RH <i>Detel</i>	1	\$ 1,456.30	960.70	\$ <i>1,456.30</i>
16	FRONT ABSORBER RH <i>new</i>	1	\$ 519.00		\$ <i>+</i> 519.00
17	FRONT KNUCKLE ARM RH <i>new</i>	1	\$ 398.70		\$ <i>+</i> 398.70
18	FRONT WHEEL HUB BEARING RH <i>new</i>	1	\$ 358.20		\$ <i>✓</i> 358.20
19	FRONT LOWER ARM RH <i>Best</i>	1	\$ 325.80		\$ <i>✓</i> 325.80
Total List Price Cost					\$ 6,264.70
PARTS DISCOUNT 20%					\$ 5,011.76

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ <i>✓</i> 30.00
2	SIDESKIRT CLIPS <i>new</i>	1 SET	\$ 30.00		\$ <i>✓</i> 30.00
3	FRONT FENDER INNER COWLING CLIPS <i>new</i>	1 SET	\$ 30.00		\$ <i>✓</i> 30.00
4	FRONT RIM (RH) <i>lit</i>	1	\$ 700.00		\$ <i>450</i> 700.00
5	SIDESKIRT RH (ACCESSORIES) <i>Amold</i>	1	\$ 480.00		\$ <i>✓</i> 480.00
6	FRONT BUMPER (ACCESSORIES) <i>Detel</i>	1	\$ 680.00		\$ <i>✓</i> 680.00
Total Special Nett Items					\$ 1,950.00

1700

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW,REPAIR ,REALIGN DAMAGED PARTS, REPLACE,BEAT AND WELD	\$ 1,400.00 <i>600</i>
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,400.00 <i>800</i>
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 60 200.00
TO REMOVE/ REFIT REAR INTERIOR UPHOSTERY	\$ X 180.00
LABOUR TO REMOVE/ REFIT / REPLACE FRONT UNDERCARRIAGE	\$ 150 180.00
TO CONDUCT WIRING CHECK AND RESET HEADLAMPS TO ITS PRE-ACCIDENT CONDITION	\$ 30 120.00
TO PERFORM COMPUTERISED WHEEL ALIGNMENT (BEFORE AND AFTER)	\$ 80 120.00
Total Others Cost	\$ 800.00
To remove and refit door fittings. <i>80. 150</i>	GRAND TOTAL <i>1800</i>
	\$ 10,561.76

CAS GARAGE PTE LTD
UEN 201828067M
1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allangoh.cas@gmail.com
Fax : 6509 9501

Adrian C
1/s 16/07/20
06 Days.

total: 5996.40
1/s: 4.8K

4.8K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: