

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST.M9-0009639-E RCB NO.06470300B

SURVEYOR COPY

M/S: JACKSON NG
 601A PUNGGOL CENTRAL
 #16-622 PUNGGOL VISTA
 SINGAPORE 821601
 TEL: 98314544
 ATTN:

UKK
12/01/20

Estimate No: MC1901285
 Date: 13 Jul 2020
 Policy No: PNPV2020-00005537
 Veh Reg No: EQ7071A
 Make/Model: NISSAN SYLPHY 1.6
 CVT ABS

Not Authorize
Liability
Recovery After Repair

Your Ref No: EQ7071A
 Claim Type: Third Party - A16
 Accident Date: 11/07/2020
 TP Veh Reg No: GBK734J

Estimate Repair Cost to Vehicle No :EQ7071A

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT	1 PC	1,199.90	✓
2 REAR BOOT EMBLEM	1 PC	46.90	✓
3 REAR BOOT SYLPHY LOGO	1 PC	87.60	✓
4 REAR BOOT PURE DRIVE XTRONIC CVT LOGO	1 PC	73.60	✓
5 REAR BOOT CHROME MOULDING TOP	1 PC	191.40	✓
6 REAR BOOT CHROME MOULDING BOTTOM	1 PC	116.00	✓
7 REAR BOOT LAMP LH & RH	2 PC	322.80	?
8 REAR BOOT HINGE LH & RH	2 PC	162.00	X
9 REAR BOOT RUBBER	1 PC	87.90	X
10 REAR BOOT INNER LOCK	1 PC	115.00	X
11 REAR BOOT INNER LOCK STRIKER	1 PC	56.90	X
12 REAR BOOT INNER LOCK SENSOR	1 PC	87.00	?
13 TAILAMP LH & RH	2 PC	752.60	?
14 TAILAMP PANEL LH & RH	2 PC	554.20	X
15 REAR BUMPER	1 PC	625.80	✓
16 REAR BUMPER SIDE RETAINER LH & RH	2 PC	72.00	?
17 REAR BUMPER CLIP	12 PC	61.20	✓
18 REAR BUMPER SPONGE CTR	1 PC	46.00	?
19 REAR BUMPER SPONGE LH & LH	2 PC	175.40	X
20 REAR BUMPER INNER BRACKET LH & RH	2 PC	100.80	?
21 REAR FENDER COWLING REAR LH & RH	2 PC	72.00	X
22 REAR END PANEL	1 PC	441.70	?
23 REAR END PANEL GARNISH	1 PC	96.40	?
		5,545.10	
	Less 10%	554.51	4,990.59
Special Nett			
24 REVERSE SENSOR	1 SET	200.00	X
25 NUMBER PLATE	1 PC	35.00	✓
		235.00	235.00
LABOUR			
26 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
27 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	60.00	501
28 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501



Scanned with CamScanner

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST-M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JACKSON NG
601A PUNGGOL CENTRAL
#16-622 PUNGGOL VISTA
SINGAPORE 821601
TEL: 98314544
ATTN:

Estimate No: MC1901285
Date: 13 Jul 2020
Policy No: PNPV2020-00005537
Veh Reg No: EQ7071A
Make/Model: NISSAN SYLPHY 1.6
CVT ABS

Your Ref No: EQ7071A
Claim Type: Third Party
Accident Date: 11/07/2020
TP Veh Reg No: GBK734J

Estimate Repair Cost to Vehicle No :EQ7071A

Description	Quantity	List Price	Amount
		S\$	S\$
29 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	301
30 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL TO KNOCK & REPAIR RR FENDER LH & RH, SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	501
31 TO SPRAY REAR BOOT, REAR BUMPER, REAR FENDER LH & RH, END PANEL.	1 PC	800.00	601
		1,720.00	1,720.00
	Total		S\$ 6,945.59
	Add GST @ 7%		486.19
	Total Amount Payable		S\$ 7,431.78

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED THIRTY ONE AND CENTS SEVENTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

