VEHICLE NO.	SGV 2384P	HONDA CIVIC
VEHICLE NO.	301 Z304F	LICIADA CIAIC

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)		1	
1	Bonnet	1 (	A 1 1072.50	T1 1
1	Bonnet inner lock	REFIX	0.00	1.00
1	Bonnet insulator	REFIX	17 0.00	Constant of the contract of th
2	Bonnet rubber stoppper @42.00		11 84.00	X
1	Front centre grille chrome assy	nlc		X
1	Front centre grille chrome badge	1	72.00	X
1	Front bumper	curl	70m 1150.00	638
1	Front bumper lower cover	1	11 275.00	X
2	Front bumper side retainers			IPC 25.20
1	Front bumper centre lower grille		157.50	
1	Front bumper LED daylight RHS		<b>ヘク 392.00</b>	X
1	Front bumper LED daylight garnish RHS	10.00	رم 224.00	$\mathbf{\hat{x}}$
1	RHS Front fender		R 671.80	X
1	RHS Front fender inner splash shield		17 214.00	
1	RHS Headlamp	cna/	SCA 985.20	912.10
1	RHS Headlamp support bracket	,	119.00	×
	M*		6013.00	
		less	20% 1202.60	20%
			4810.40	
	SPECIAL NETT ITEMS	W		
1set	Front bumper clips		nec 60.00	35
1	Front license plate	REFIX	17 0.00	×
1	Front license plate garnish	REFIX	11 0.00	(文)
1set	Front centre radiator grille clips		W 60.00	) <u> </u>
1set	Front fender inner shield clips		<b>ハ</b> へ 60.00	×
1set	Bonnet insulator clips		A1 80.00	×
	A second service of the second service of th	TOTAL PARTS	5070.40	

ولا. بلا. بما رم 202 126024 1915,24

Not Anthorised

All SOUT

The photo Ather up in

3 days.

VEHICLE NO. SGY 2384P HONDA CIVIC

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; replace damaged parts and components	800.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	750.00	400
3	To remove, check/refix wiring system at accident damaged areas and focus headlamp beam	150.00	20
4	To perform anti-rust treatment on affected areas	120.00 🔥 🐧	1
	Labour Total :	1820.00	18 7 7
	TOTAL (PARTS & LABOUR):	6890.40	Talk Sector Control of the

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: