

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No. 19960/198R GST Reg. No. 19-960/198-R | | | | | |
|--|--|--|---------|-------------------|------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
| AUTO & GENERAL INSURANCE (S) PL | | | Ref: | CS/AGI20007287/A | Aqf3q2 | |
| (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 | | | Date : | 29-10-2020 AGI | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | SMC 7582X | Veh. In | spected | SMN 206X | |
| | Policy No. | | Covera | ıge (\$) | 0.00 | |
| | Claim No. | C10006719 | Excess | s (\$) | 0.00 | |
| | Assign From | IVY RATILLA | Assign | Date | 14/07/2020 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | TOYOTA VIOS | c.c | | 1496 | |
| | Engine No. | HIDDEN | Year of | Reg. | 2019 | |
| | Chassis No. | MR2B23F3601179931 | Colour | | SILVER | |
| | Odometer | 27959 | Steerin | ıg | IN ORDER | |
| | Brakes | IN ORDER | Modific | cation | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. | Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 185/60 R15 | YOKOH | AMA | 6 mm | |
| | L/H Front Tyre | 185/60 R15 | YOKOH | AMA | 6 mm | |
| | R/H Rear Tyre | 185/60 R15 | YOKOH | AMA | 6 mm | |
| | L/H Rear Tyre | 185/60 R15 | YOKOH | AMA | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 14/07/2020 | Inspec | tion Date | 15/07/2020 | |
| | Survey held at | at KANG CAR REPAIRERS PTE LTD | | | | |
| | | NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: