

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department \ Motor Claim

Estimate No: **EST2000132**
Date: 14 Jul 2020

Veh Reg No: **SMN206X**
Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3601179931
Reg. Date: 23/07/2019
Your Ref No: SMC7582X

Claim Type: Third Party
Accident Date: 14/07/2020
TP Veh Reg No: SMC7582X

Xiao Chen.

Estimate Repair Cost to Vehicle No :SMN206X

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC REAR BUMPER <i>Defund</i>	582.70	✓ 482
2	1 PC REAR BUMPER REINFORCEMENT <i>cut</i>	386.30	✓ 316
3	1 PC REAR BUMPER RETAINER LH <i>cut</i>	149.90	✓ 75
4	1 PC REAR BUMPER RETAINER (SMALL) LH <i>cut</i>	68.80	✓
5	1 PC REAR BUMPER REFLECTOR - LH <i>new</i>	98.90	✗
6	1 PC REAR PANEL <i>new</i>	630.40	✗
7	1 PC REAR PANEL TRIM <i>new</i>	232.20	✗
8	1 PC TAIL LAMP LH <i>new</i>	395.70	✗
		2,544.90	
Less 25%		636.23	1,908.70
Special Net			
9	1 SET REAR BUMPER CLIPS <i>new</i>	40.00	✓
10	1 SET REAR BUMPER STICKER <i>new</i>	195.00	✓ 160
11	2 PCS "L" PLATE BRACKET <i>new</i>	70.00	✓ 50
12	1 SET REAR PANEL TRIM CLIPS <i>new</i>	30.00	✗
		335.00	335.00
Labour			
13	1 TO CHECK WIRING	50.00	30
14	1 P TO REPLACE STICKER	100.00	30
15	1 TO SPRAY UNDERSEAL	100.00	✗
16	1 (REAR) TO SPRAY PAINTING	800.00	400
17	1 TO REMOVE AND REFIT INNER TRIM	100.00	✗
18	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	800.00	300
		1,950.00	1,950.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2000132

Date: 14 Jul 2020

Veh Reg No: SMN206X

Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3601179931

Reg. Date: 23/07/2019

Your Ref No: SMC7582X

Claim Type: Third Party
Accident Date: 14/07/2020
TP Veh Reg No: SMC7582X

Estimate Repair Cost to Vehicle No :SMN206X

Quantity	Description	List Price	Amount
		SS	SS
	Total		S\$ 4,193.70
	Add GST @ 7%		293.56
	Total Amount Payable		S\$ 4,487.26

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FOUR HUNDRED EIGHTY SEVEN AND CENTS TWENTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
h/s 15/07/20
03 Days.

total: 1900.77 (P/P)

1900.77