



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 669536.
Tel : 6484 1221 Fax : 6484 7829
385 Sin Ming Drive (Inside Vicom) Singapore 575718.
Tel : 6753 2112 Fax : 6451 0394
Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Not Attached
1-B.1
Running 88 points

Spare Parts

Vehicle No. : **SMM 2959 Z** Submit By : *28 days* Carmen Lim
Make & Model : **TOYOTA NOAH** Year Manufacture : **2019 Jun**
Chassis No. : **ZWR800384279** Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen <i>Shorten</i>	1			✓
2	Rear windscreen moulding <i>Ne</i>	1			✓
3	Rear windscreen sealant <i>Ne</i>	1			✓
4	Reverse sensor <i>Short</i>	2			✓
5	Rear number plate <i>Ne</i>	1			✓
6	Rear No.plate lamp LH	1			✓
7	Rear No.plate lamp RH	1			✓
8	Rear bumper <i>Tn</i>	1			✓
9	Rear bumper clip <i>Ne</i>	10			✓
10	Rear bumper side retainer LH <i>Dit</i>	1			✓
11	Rear bumper side retainer RH <i>CM</i>	1			✓
12	Rear bumper bracket LH <i>R</i>	1			X
13	Rear bumper bracket RH <i>R</i>	1			✓
14	Rear bumper reflector LH <i>Sn</i>	1			X
15	Rear bumper reflector RH <i>Bv</i>	1			✓
16	Rear bumper tow cover <i>Sn</i>	1			X
17	Tail door <i>R</i>	1			✓
18	Tail door lock <i>Tn</i>	1			✓
19	Tail door lock catch <i>Dit</i>	1			✓
20	Tail door emblem <i>Ne</i>	1			✓
21	Tail door chrome <i>CM</i>	1			✓
22	Wording "HYBRID SYNERGY DRIVE" <i>Ne</i>	1			✓
23	Tail door trim - completed <i>CM</i>	1			✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare PartsVehicle No. :
Make & Model :
Chassis No. :**SMM 2959 Z**TOYOTA NOAH
ZWR800384279

Submit By :

Year Manufacture :

Engine No. :

Carmen Lim

2019 Jun

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door trim clip	10			✓
25	Taildoor hinge LH	1			✓
26	Taildoor hinge RH	1			✓
27	Taildoor absorber LH	1			?
28	Taildoor absorber RH	1			✓
29	Rear recorder	1			✓
30	Reaverse camera	1			✓
31	Rear wiper motor	1			X
32	Tail end panel - inner	1			✓
33	Tail end panel - outer	1			✓
34	Tail end panel garnish	1			✓
35	Tail end panel garnish clip	10			✓
36	Tail lamp RH	1			✓
37	Tail lamp inner panel RH (completed)	1			✓
38	Tail lamp lower panel RH	1			✓
39	Tail lamp LH	1			?
40	Tail lamp clip	4			✓
41	Spare tyre well panel	1			✓
42	Spare tyre board	1			?
43	RH rear fender - upper	1			✓
44	RH rear fender - lower	1			✓
45	RH rear fender undershield	1			✓
46	RH rear fender undershield clip	10			✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SMM 2959 Z** Submit By : **Carmen Lim**
 Make & Model : **TOYOTA NOAH** Year Manufacture : **2019 Jun**
 Chassis No. : **ZWR600384278** Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	RH rear inner trim - upper <i>D/V</i>	1			✓
48	RH rear inner trim - lower <i>CM</i>	1			✓
49	RH rear inner trim clip <i>Me</i>	10			✓
50	RH rear fender glass <i>Shortens</i>	1			✓
51	RH rear fender glass sealant <i>Me</i>	1			✓
52	RH rear fender glass outer moulding <i>Me</i>	1			✓
53	RH rear fender inner panel (completed) <i>g</i>	1			✓
54	RH rear lower arm	1			?
55	RH rear knuckle arm	1			?
56	RH rear knuckle bearing	1			?
57	RH rear wheel hub	1			?
58	RH rear wheel hub lock nut	1			?
59	RH rear shock absorber	1			?
60	RH rear shock absorber stopper	1			?
61	RH rear shock absorber top mounting	1			?
62	RH rear drive shaft <i>N/P</i>	1			X
63	RH rear trailing arm <i>N/P</i>	1			X
64	RH rear anti roll bar link	1			?
65	RH rear chassis - completed	1			?
66	RH rear wheel housing	1			?
67	RH rear rim	1			?
68	RH rear tyre <i>Pe</i>	1			7024
69	Rear axle	1			?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SMM 2959 Z**
 Make & Model : **TOYOTA NOAH**
 Chassis No : **ZWR800384279**

Submit By : **Carmen Lim**
 Year Manufacture : **2019 Jun**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Rear aircon compressor <i>Blower 914</i>	1			✓
71	Rear aircon compressor casing <i>nn</i>	1			X
72	Rear aircon compressor pipe	1			?
73	RH rear sliding door <i>Bu</i>	1			✓
74	RH rear sliding door top hinge	1			?
75	RH rear sliding door bottom hinge	1			?
76	RH rear sliding door roller motor	1			?
77	RH rear sliding door railing motor	1			✓
78	RH rear door lock <i>Tu</i>	1			?
79	RH rear door weatherstrip	1			?
80	RH rear weatherstrip (body)	1			✓
81	RHR door glass outer moulding <i>Bu</i>	1			?
82	RH rear door stand pillar garnish	1			?
83	RH rear door inner trim	1			?
84	RH rear door inner trim clip	10			?
85	RH front door <i>R</i>	1			X
86	RH front door hinge top <i>R</i>	1			X
87	RH front door hinge bottom <i>R</i>	1			X
88	RH front door glass outer moulding <i>Bu</i>	1			✓
89	Roof top <i>Bu</i>	1			✓
90	Roof top lining <i>De form</i>	1			✓
91	Roof top lining clip <i>nn</i>	10			✓
92	Roof top moulding RH <i>nn</i>	1			✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

are Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SMM 2959 Z

TOYOTA NOAH
 ZNR800384279

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim
 2019 Jun

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Roof top garnish RH	1			✓
94	Third brake light	1			X
95	LH rear fender - upper	1			X
96	LH rear fender - lower	1			X
97	LH rear fender undershield	1			X
98	LH rear fender undershield clip	10			X
99	LH rear inner trim - upper	1			X
100	LH rear inner trim - lower	1			?
101	LH rear inner trim clip	1			?
102	LH rear fender glass sealant	1			X
103	LH rear fender glass outer moulding	1			X
104	LH rear sliding door	1			X
105	LH rear sliding door top hinge	1			X
106	LH rear sliding door bottom hinge	1			X
107	LHR door glass outer moulding	1			X
108	Rear Seat back rest rack LH	1			✓
109	Rear Seat rest rack LH	1			✓
110	Rear Seat back rest rack RH	1			✓
111	Rear Seat rest rack RH	1			✓
112	Driver seat back rest rack	1			✓
113	Driver seat rest rack	1			✓
114	Driver seat safety belt	1			X
115	Airbag control unit	1			?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SMM 2959 Z** Submit By : **Carmen Lim**
 Make & Model : **TOYOTA NOAH** Year Manufacture : **2019 Jun**
 Chassis No. : **ZWR800384279** Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
116	Petrol tank cover <i>Am</i>	1			X
117	Petrol tank cover rivet <i>vv</i>	1			X
118	Exhaust pipe <i>Rg</i>	1			✓
119	Exhaust pipe insulator	1			?
120	Exhaust pipe insulator clip	10			?
121	Exhaust pipe mounting	2			?
122	PHV Sticker <i>Am</i>	1			✓
123					
124					
125					
126					
127					
128					
129					
130					
131					
132					
133					
134					
135					
136					
137					
138					

I, the undersigned, hereby certify that the repair of the following parts is necessary and that the repair is in accordance with the terms of the insurance policy.

- To insure before and after spray painting
- To display damaged and undamaged money
- Parts prices are subject to confirmation
- Third party survey is one of the repairer's responsibilities
- No illegal modification is allowed
- Supplemental or secondary must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

B11 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.
Tel : 6484 1221 Fax : 6484 7829
385 Sim Ming Drive (Inside Vicom) Singapore 575718.
Tel : 6733 2112 Fax : 6481 8994
Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Labour

Vehicle No. : **SMM 2959 Z** Submit By : **Carmen Lim**
Make & Model : **TOYOTA NOAH** Year of Manufacture : **2019 Jun**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA, (TAILDOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER, RH SLIDING DOOR, RHF DOOR, LHR FENDER, LH SLIDING DOOR, RHR CHASSIS, RHR "C" PILLAR, ROOF TOP, FLOOR PANEL)	\$3,600.00	3000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA, (TAILDOOR, REAR BUMPER, END PANEL, SPARE TYRE WELL PANEL, RHR FENDER, RH SLIDING DOOR, RHF DOOR, LHR FENDER, LH SLIDING DOOR, RHR CHASSIS, RHR "C" PILLAR, ROOF TOP, FLOOR PANEL)	\$3,200.00	2600
3	To check wiring	\$50.00	30
4	To remove & refit reverse sensor	\$120.00	30
5	To buff coat	\$50.00	200
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	120
7	To remove & refit undercarriage to assist work load.	\$300.00	220
8	To do wheel alignment.	\$120.00	60
9	Towing (5.11)	\$120.00	?

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : **SMM 2959 Z** Submit By : **Carmen Lim**
 Make & Model : **TOYOTA NOAH** Year of Manufacture : **2019 Jun**

SNo	Labour Description	Estimated Price	Adjusted Price
10	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
11	To remove & refit rear windscreen.	\$120.00	✓
12	To reset airbag control unit.	\$250.00	?
13	To buff coat.	\$300.00	210
14	To re-align rear chassis.	\$300.00	150
15	To remove & refit inner seat & upholstery to assist work load.	\$600.00	200
16	To remove & refit roof lining, inner trim to assist work load.	\$450.00	
17	To remove & refit exhaust system to assist work load.	\$150.00	60
18	To remove & refit petrol tank to assist work load.	\$150.00	60
19	To transfer hand mechanism to new boot.	\$120.00	60
20	To conduct water leakage tests to ensure proper fit and sealing.	\$120.00	30
21	To remove & refit rear axle to assist work load.	\$300.00	✓

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.