

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 230L**AAD2007-049***Not Notion**1/1mp @ 1700/h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 230L

VF1ABL15AUC282168

RENAULT

LATITUDE

11.7.2020

FCIL

16/10/2015

PART	
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER BRACKET FRT RH (Headlamp Lower)
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	HEADLAMP RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	BONNET
1	WIPER RESERVOIR MOTOR
1	WIPER RESERVOIR
1	WIPER RESERVOIR NECK

LIST	
\$	<i>Bul/dio</i> 747.20 ✓
\$	<i>SL</i> 344.70 X
\$	<i>SL</i> 116.47 X
\$	<i>SL</i> 394.68 X
\$	<i>D.Y</i> 101.40 ✓
\$	<i>SL</i> 292.50 X
\$	<i>SL</i> 147.00 X
\$	<i>SL</i> 207.21 X
\$	<i>SL</i> 743.60 X
\$	<i>SL</i> 437.10 ✓
\$	<i>SL</i> 191.40
\$	<i>SL</i> 969.90
\$	<i>SL</i> 225.36
\$	<i>SL</i> 686.00
\$	<i>SL</i> 592.70
\$	<i>SL</i> 1,312.70
\$	<i>SL</i> 82.60
\$	<i>SL</i> 179.60
\$	<i>SL</i> 29.30
TOTAL	\$ 7,801.42
10%	\$ 780.14
	\$ 7,021.28

Special Nett

1	BUMPER CLIP FRT
1	BUMPER BRACKET CLIP FRT RH

\$	<i>SL</i> 75.00 ✓
\$	<i>SL</i> 50.00 X

Trans-cab Auto Services Pte Ltd**AAD2007-049**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 230L

1 BUMPER RETAINER CLIP FRT RH	\$	nn	60.00	}	X
1 BUMPER GRILLE LOWER CLIP	\$	nn	69.00		
1SET BUMPER FOG LAMP GRILLE CLIP	\$	nn	55.00		
1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00		
2 FRAME FULL SUPPORT PANEL NUT	\$	nn	40.00		
2 FRAME FULL SUPPORT PANEL STUD	\$	nn	50.00		
1 WHEELARCH CLIP FRT RH	\$	nn	60.00		
1SET Front licence plate with holder	\$	nn	120.00		
1SET RADIATOR GRILLE SCREW	\$	nn	50.00		
1SET RADIATOR GRILLE FRAME CLIP	\$	nn	55.00		
TOTAL	\$		754.00		

TOTAL PARTS \$ 7,775.28**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,500.00 400

Putty and spray painting of the affected portion.

\$ 4,500.00 400

To transfer of front fender fittings, attachment and perform water seepage test.

\$ nn 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 100

To rust-proofing and apply undercoat of the affected areas.

\$ 170.00 300

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ nn 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2007-049**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 230L**TOTAL \$ 10,060.00****Over All Total \$ 17,835.28****LUMP SUM (REPAIR DAY)****28 DAYS***2 days***For Official Use**Prepared By : _____
(Accident Dept)Verify By : _____
(Accident Workshop)Checked By : _____
(Finance Dept)LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: