

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 230L**AAD2007-049***Not Authentic**1/1mp @ 1700ph*

Vehicle No.:
Chassis No.:
Vehicle Make: **14 JUL 2020**
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHD 230L
VF1ABL15AUC282168
RENAULT
LATITUDE
11.7.2020
FCIL
16/10/2015

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bud 7.0</i> 747.20 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 344.70 X
1	BUMPER BRACKET FRT RH (Headlamp Lower)	\$	<i>Sn</i> 116.47 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>D.7</i> 101.40 ✓
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 292.50 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 147.00 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
1	HEADLAMP RH	\$	<i>Sn</i> 743.60 X
1	FENDER PANEL FRT RH	\$	<i>Sn</i> 437.10 ✓
1	WHEELARCH FRT RH	\$	<i>Sn</i> 191.40
1	RADIATOR GRILLE	\$	<i>Sn</i> 969.90
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 686.00
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 592.70 } X
1	BONNET	\$	<i>R</i> 1,312.70
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 82.60
1	WIPER RESERVOIR	\$	<i>Sn</i> 179.60
1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 29.30
TOTAL		\$	7,801.42
10%		\$	780.14
		\$	7,021.28

Special Nett

1	BUMPER CLIP FRT	\$	<i>Sn</i> 75.00 ✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>Sn</i> 50.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 230L**AAD2007-049**

1 BUMPER RETAINER CLIP FRT RH	\$	nn	60.00
1 BUMPER GRILLE LOWER CLIP	\$	nn	69.00
1SET BUMPER FOG LAMP GRILLE CLIP	\$	nn	55.00
1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00
2 FRAME FULL SUPPORT PANEL NUT	\$	nn	40.00
2 FRAME FULL SUPPORT PANEL STUD	\$	nn	50.00
1 WHEELARCH CLIP FRT RH	\$	nn	60.00
1SET Front licence plate with holder	\$	nn	120.00
1SET RADIATOR GRILLE SCREW	\$	nn	50.00
1SET RADIATOR GRILLE FRAME CLIP	\$	nn	55.00
TOTAL	\$		754.00

TOTAL PARTS \$ 7,775.28**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,500.00 *400*

Putty and spray painting of the affected portion.

\$ 4,500.00 *480*

To transfer of front fender fittings, attachment and perform water seepage test.

\$ nn 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *100*

To rust-proofing and apply undercoat of the affected areas.

\$ 170.00 *300*

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ nn 170.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 *X*

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHD 230L

AAD2007-049

TOTAL	\$	10,060.00
Over All Total	\$	17,835.28

LUMP SUM (REPAIR DAY)

28 DAYS

20 days

For Official Use

Prepared By :	_____
	(Accident Dept)
Verify By :	_____
	(Accident Workshop)
Checked By :	_____
	(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: