

ALG/20002889/Me

ASSIGNMENT

ASS. REG. AV.

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Poh Yew Chye
15A Jin Senang
Singapore 769549

Not Admitted
Person B4 pass

L/Snp @ 3800/v

4 days

Vehicle No : SBD 908 L
Make : Ford Focus
Year : 2019

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

pc	Rear tail-gate assy	R X	1850 X
pc	Rear tail-gate inner lock	R X	285 X
pc	Rear tail-gate emblem - Focus	NI	65
pc	Rear tail-gate emblem - Titanium	NI	72
pc	Rear tail-gate emblem	NI	55
pc	Rear bumper	NI	1413
pc	Rear bumper reinforcement	? NI	756
pc	Rear bumper sponge	NI	533
pc	Rear lower bumper	DI	800
cs	Rear bumper reverse sensor	70225-0	210
cs	Rear bumper side retainer	015017-0105	210
C	Rear bumper tow cover	NI	65
2	Rear end panel	R X Bent	550 X
:	Rear end panel inner garnish	NI X	255 X
	rear bumper reflector	R/H	255

\$7264

Less 15 % **\$6174.40**

Rear bumper clip

\$2.00 *mu* \$30.00

Charges

2/renew the above parts including knocking, welding & cutting.

600
550

& spray paint on accident affected portion

\$900.00 6000

and reconnect wiring

\$40.00 157

new rear bumper sensor and to reset to factory specification

\$200.00 601

st proofing

$$\begin{array}{r} \sim \sim \sim \\ \$100.00 \\ \hline \$8344.40 \end{array}$$

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: