



Pte Ltd

India International Insurance Pte Ltd

64 Cecil Street #05-00

IOB Building

Singapore 409711

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

Vehicle number	GBJ1405H
Make / Model	TOYOTA/HIACE VAN
Chassis number	JTFH02P400246707
Accident date	11 July 2020
Reference	

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT PANEL	898.66 del
1	FRONT GRILLE UPPER	428.30 x nn
1	FRONT GRILLE LOWER	439.81 x nn
1	FRONT EMBLEM	121.43 x nn.
1	FRONT LH HEADLAMP	1429.50 cut ✓ 1000
1	FRONT LH HEADLAMP BRACKET	121.20 x nn
1	FRONT BUMPER	645.84 Rs
2	FRONT BUMPER BRACKET	182.10 x nn
1	FRONT BUMPER GRILLE LH	182.25 x nn.
		4449.09
Less 25 %		1112.27
Subtotal		3336.82
Balance C/F		3336.82
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP	30.00 x nn
1 SET	FRONT GRILLE CIIP	20.00 x nn
Subtotal		50.00
Balance C/F		3386.82
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		3386.82
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 20-
2	PANEL BEATING AND RENEW PARTS ON AFFECTED AREAS	500.00 300.
3	SPRAY PAINTING ON AFFECTED AREAS	600.00 400.
4	APPLY ANTI RUST ON AFFECTED AREAS	100.00 30
Subtotal		1260.00
Grand total		4646.82

Tan Kah 92495747
WP' Impson
Resin after upal.

15/7/20e 1pm 3 days
tan Kah 11hantun

1423.99
760
2183.99
4581750 3 days.