

1000 Bukit Merah

Saka Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 97650577

TP111
Caelia

ESTIMATE

Repair Code : CLM16321

Date in : 13/07/2020

Vehicle Num. : SMA4912H

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU10J027944/2ZR0B82210

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Deformed</i>	1	523.90	✓ 523.90
REAR BUMPER LOWER COVER <i>Cracked</i>	1	179.00	✓ 179.00
REAR BUMPER LOWER SPOILER <i>Deformed</i>	1	721.00	✓ 721.00
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	350.50	✓ 350.50
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Beast</i>	2	198.70	✓ 397.40
REAR BUMPER SIDE RETAINER L/R <i>As</i>	2	98.00	✓ 196.00
REAR END PANEL <i>Repair</i>	1	781.45	✓ 781.45
REAR END PANEL ANTENNA SENSOR <i>Cracked</i>	1	485.00	150 485.00
REAR END PANEL INNER TOP GARNISH <i>Deformed</i>	1	287.90	✓ 287.90
REAR RH TAILLAMP <i>Cracked</i>	1	630.00	✓ 630.00
REAR RH TAILLAMP BACK RUBBER GASKET <i>As</i>	1	69.50	20 69.50
REAR RH TAILLAMP LOWER BRACKET <i>As</i>	1	68.00	✓ 68.00
REAR TAILGATE 'HYBRID' EMBLEM <i>As</i>	1	50.00	✓ 50.00
REAR TAILGATE 'PRIUS' EMBLEM <i>As</i>	1	52.30	✓ 52.30
REAR TAILGATE WEATHER STRIP <i>As</i>	1	360.70	✓ 360.70

*** This is a computer-generated document which requires no signature.***

page 1

3558

2668.50

n51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 97650577

ESTIMATE

Repair Code : CLM16321
Date in : 13/07/2020
Vehicle Num. : SMA4912H
Model : TOYOTA PRIUS PLUS (AUTO)
Chassis/Eng# : JTDZS3EU10J027944/2ZR0B82210

Subtotal before discount		5,152.65
Percentage discount 25%		1,288.16
Sub-total 1		3,864.49
REAR BUMPER CLIPS - SET	1	50.00 30 50.00
REAR BUMPER LOWER COVER CLIPS - SET	1	20.00 ✓ 20.00
REAR BUMPER LOWER SPOILER CLIPS - SET	1	60.00 30 60.00
REAR BUMPER REVERSE SENSOR	1	250.00 20 250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	20.00 ✓ 20.00
REAR RH TAILLAMP CLIPS - SET	1	30.00 20 30.00
Subtotal before discount		430.00
Percentage discount 0%		0.00
Sub-total 2		430.00
Parts-total		4,294.49

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

Labour Total 1,770.00

Parts & Labour Total 6,064.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer-generated document which requires no signature.***

page 2

Total 4118.50

L/S 3.3K.

04 Days

33K