



Supplementary

Estimate No. : **b1 55528**
 Date Estimated : **15/07/2020**
 Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -

Tan Kok Wah
35 Amber Road
#12-16 The Seaview Condominium

Singapore 439945

- ACCOUNT - 115
United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGZ8999X	WBAKS820300G66431	19/09/2014	X5 M50D SAV	0

DESCRIPTION

ORIGINAL PRICE	DISC. %	NETT
----------------	---------	------

DESCRIPTION

UNIT PRICE	QTY	DISC. %	NETT
------------	-----	---------	------

TORX SCREW **nec** /
 # SELF-LOCKING COLLAR NUT **nec** /
 # REAR GUIDE SUPPORT **bt** / Repeated
 # HEX NUT WITH FLANGE **nec** /
 # (SIL) REAR PNEUMATIC SPRING **nw** /
 # RR RH WHEEL ARCH TRIM PANEL **scr** /
 # EXPANDING RIVET BLACK **nec** /
 # RR RH WHEEL WELL TRIM PIECE PRIMED **scr** /

7.85	4.00		31.40
7.60	2.00		15.20
175.30	1.00		175.30
3.25	2.00		6.50
831.60	1.00		831.60
234.25	1.00		234.25
1.40	10.00		14.00
261.20	1.00		261.20

SUPPLEMENTARY ITEMS

Total Labour :	1,569.45
Total Parts :	1,569.45
Total Labour & Parts :	750.00
Deduction for Excess :	819.45
Total Repair Costs less Excess:	57.36
GST @7%:	876.81
Grand Total :	