

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 6-Jul-20

INSURANCE:

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA8317J

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER <i>form</i>	1	\$458.60	\$458.60
REAR BUMPER SIDE RETAINER <i>SVC</i>	1	\$112.70	\$112.70
REAR BUMPER CLIPS <i>4pc</i>	1	\$22.00	\$22.00
TAIL LAMP ASSY (UPPER) <i>HH</i>	1	\$557.90	\$557.90
TAIL LAMP ASSY (LOWER) <i>HH</i>	1	\$548.40	\$548.40
REAR FIBER TOOL BOX TRIM (LH) <i>HH</i>	1	\$598.00	\$598.00
REAR FENDER, LH <i>Buc</i>	1	\$836.70	\$836.70
REAR FENDER INNER PANEL (LH) <i>Dentel repn</i>	1	\$728.00	\$728.00
REAR FENDER OUTER PANEL, LH <i>Dentel</i>	1	\$486.00	\$486.00
REAR FENDER REINFORCEMENT, ROCKER, PANEL, LH <i>HH</i>	1	\$552.30	\$552.30
REAR FENDER PANEL, ROOF SIDE OUTER, LH <i>HH</i>	1	\$311.00	\$311.00
REAR FENDER EXTENSION, ROOF SIDE INNER FRT, LH <i>HH</i>	1	\$265.10	\$265.10
REAR FLOOR PANEL SIDE (LH) <i>HH</i>	1	\$276.20	\$276.20
REAR FENDER SHIELD (LH) <i>deformed</i>	1	\$174.20	\$174.20
REAR FENDER TRIMBOARD (LH) <i>HH</i>	1	\$725.00	\$725.00
REAR FENDER AIR DUCT <i>HH</i>	1	\$165.10	\$165.10
REAR FENDER TOP PANEL INNER <i>HH</i>	1	\$340.20	\$340.20
REAR CHASSIS MEMBER <i>HH</i>	1	\$1,180.80	\$1,180.80
REAR FLOOR PANEL SIDE (LH) <i>HH</i>	1	\$717.60	\$717.60
REAR FLOOR BOARD (LH) <i>HH</i>	1	\$823.40	\$823.40
REAR DOOR RUBBR SEAL OUTER <i>HH</i>	1	\$257.90	\$257.90
PANEL SUB-ASSY, REAR DOOR, LH <i>Dentel</i>	1	\$1,258.30	\$1,258.30
REAR DOOR HINGE UPPER <i>HH</i>	1	\$82.30	\$82.30
REAR DOOR HINGE LOWER <i>HH</i>	1	\$82.30	\$82.30
REAR DOOR CHECK <i>HH</i>	1	\$153.00	\$153.00
REAR DOOR TRIMBOARD	1	\$725.00	\$725.00
REAR DOOR INNER LOCK <i>HH</i>	1	\$644.70	\$644.70
MOTOR, POWER WINDOW REGULATOR FRT, LH <i>HH</i>	1	\$941.80	\$941.80
REGULATOR, FRONT DOOR WINDOW REAR, LH <i>HH</i>	1	\$228.40	\$228.40
REAR DOOR OUTER HANDLE <i>cut</i>	1	\$93.00	\$93.00
Rocker Panel Outer Garnish <i>broken</i>	1	\$576.00	\$576.00
Rocker Panel Outer <i>HH</i>	1	\$519.80	\$519.80
Rocker Panel Enforcement (LH) <i>HH</i>	1	\$ 974.30	\$974.30
Rocker Panel Inner(LH) <i>HH</i>	1	\$ 752.60	\$752.60
Rocker Panel Step Garnish(Rear)(LH) <i>HH</i>	1	\$ 178.30	\$178.30
REAR TYRE (LH) <i>form</i>	1	\$216.00	\$216.00
REAR TYRE RIM (LH) <i>2 ft</i>	1	\$1,555.00	\$1,555.00
REAR WHEEL HUB CAP (LH) <i>cut</i>	1	\$177.70	\$177.70
REAR WHEEL BEARING & HUB assy <i>2 Dentel</i>	1	\$610.20	\$610.20
REAR CROSS MEMBER <i>2 distorted</i>	1	\$2,200.40	\$2,200.40
REAR SHOCK ABSORBER <i>2 distorted</i>	1	\$118.30	\$118.30

REAR SHOCK ABSORBER MOUNTING <i>HH</i>	1	\$125.30	\$125.30	X
REAR LOWER ARM <i>2 distal</i>	1	\$497.50	\$497.50	✓
REAR UPPER ARM <i>2 distal</i>	1	\$356.80	\$356.80	✓
REAR KNUCKLE ARM <i>2 distal</i>	1	\$810.60	\$810.60	✓
REAR COIL SPRING <i>HH</i>	1	\$191.40	\$191.40	X
REAR COIL SPRING MOUNTING <i>HH</i>	1	\$125.70	\$125.70	X
REAR BRAKE ABS SENSOR (WIRE) <i>HH</i>	1	\$278.80	\$278.80	X
REAR STABILIZER BAR <i>2 distal</i>	1	\$311.50	\$311.50	✓
REAR STABILIZER LINK <i>2 distal</i>	1	\$151.60	\$151.60	✓
REAR TRAILING ARM <i>2 distal</i>	1	\$314.20	\$314.20	✓
REAR ASSIST ARM <i>2 distal</i>	1	\$342.20	\$342.20	✓
REAR HEIGHT SENSOR LH only <i>HH 1st / Down</i>	1	\$789.30	\$789.30	✓
REAR BRAKE HOSE <i>HH</i>	1	\$90.70	\$90.70	X
REAR BRAKE CALIPER <i>HH</i>	1	\$842.90	\$842.90	X
REAR BRAKE DISC ROTOR <i>HH</i>	1	\$416.50	\$416.50	X
RADIATOR GRILLE <i>2 defined</i>	1	\$438.00	\$438.00	✓
RADIATOR GRILLE EMBLEM <i>2 HH</i>	1	\$88.00	\$88.00	✓
FRONT BUMPER COVER <i>HH</i>	1	\$499.90	\$499.90	✓
FRONT BUMPER REINFORCEMENT <i>HH</i>	1	\$696.40	\$696.40	✓
FRONT BUMPER REINFORCEMENT ABSORBER <i>o/s HH</i>	1	\$115.70	\$115.70	✓
FRONT BUMPER LOWER REINFORCEMENT <i>HH</i>	1	\$364.20	\$364.20	✓
FRONT BUMPER LOWER REINFORCEMENT BRACKET <i>o/s HH</i>	1	\$330.00	\$330.00	✓
FRONT BUMPER SPONGE <i>HH</i>	1	\$78.80	\$78.80	✓
FRONT BUMPER LOWER GRILLE <i>2 defined</i>	1	\$148.60	\$148.60	✓
LAMP ASSY, FOG, RH <i>HH 1st / mostly broken</i>	1	\$920.00	\$920.00	✓
FRONT BUMPER CLIPS <i>HH</i>	1	\$22.00	\$22.00	✓
FRONT BUMPER SIDE RETAINER <i>HH mostly crack o/s</i>	1	\$77.00	\$77.00	✓
FRONT BUMPER TOP GARNISH <i>HH</i>	1	\$225.40	\$225.40	X
COVER, FRONT BUMPER HOLE, RH <i>SVC</i>	1	\$28.38	\$28.38	X
ABSORBER, FRONT BUMPER, LOWER <i>2 defined / HH</i>	1	\$127.70	\$127.70	✓
UNIT ASSY, HEADLAMP, RH (LED) <i>2 mostly broken</i>	1	\$3,455.00	\$3,455.00	✓
HEADLAMP ECU <i>HH</i>	1	\$682.60	\$682.60	X
HEAD LAMP PANEL (RH) <i>HH Dental</i>	1	\$240.10	\$240.10	✓
TOP PANEL CENTRE <i>HH</i>	1	\$364.98	\$364.98	X
TOP PANEL SIDE <i>HH o/s Dental</i>	1	\$145.90	\$145.90	✓
RADIATOR ASSY <i>HH 1st</i>	1	\$1,841.80	\$1,841.80	✓
COOLANT <i>HH</i>	1	\$45.00	\$45.00	X
DEFLECTOR, RADIATOR SIDE, RH <i>HH defined</i>	1	\$83.50	\$83.50	✓
RADIATOR FAN BLADE (RH) <i>HH</i>	1	\$233.10	\$233.10	X
RADIATOR FAN MOTOR (RH) <i>HH</i>	1	\$543.70	\$543.70	X
RADIATOR FAN COWLING (RH) <i>HH</i>	1	\$451.30	\$451.30	X
CONDENSER ASSY, W/RECEIVER <i>HH 1st</i>	1	\$1,336.60	\$1,336.60	✓
FENDER SUB-ASSY, FRONT RH <i>HH 1st</i>	1	\$945.30	\$945.30	X
FRONT FENDER SHIELD <i>HH</i>	1	\$198.50	\$198.50	X
FRONT FENDER SHIELD CLIP <i>HH</i>	1	\$14.90	\$14.90	X
FRONT FENDER HYBRID EMBLEM, RH <i>SVC</i>	1	\$86.50	\$86.50	X
BRACKET, FRONT SIDE PANEL, RH <i>HH</i>	1	\$86.30	\$86.30	X
SUB TOTAL				
LESS 20% <i>25%</i>			\$42,784.66	
DISCOUNTED TOTAL			\$8,556.93	
			\$34,227.73	

REAR BUMPER RUBBER MAT <i>HH</i>	SN	1	\$50.00	\$50.00	X
REAR BUMPER ADVERTISEMENT <i>Heu</i>	SN	21	\$120.00	\$240.00	✓
REAR FENDER ADVERTISEMENT LOGO (LH) <i>Heu</i>	SN	1	\$100.00	\$100.00	✓
REAR DOOR COMFORT & APPS STICKER <i>Heu</i>	SN	1	\$80.00	\$80.00	✓
REAR DOOR ADVERTISEMENT LOGO <i>Heu</i>	SN	1	\$100.00	\$100.00	✓
FRONT NO. PLATE <i>HH</i>	SN	1	\$25.00	\$25.00	X
FRONT NO. PLATE TRIM COVER <i>HH</i>	SN	1	\$30.00	\$30.00	X
FRONT NO. PLATE GARNISH <i>HH</i>	SN	1	\$99.00	\$99.00	X
FRONT FENDER ADVERTISEMENT LOGO (RH) <i>Heu</i>	SN	1	\$100.00	\$100.00	✓
SUB TOTAL					
				\$824.00	
Labour Charge					
Panel Beating		1	\$2,000.00	\$2,000.00	1200/-
Spray Painting Charge		1	\$1,800.00	\$1,800.00	900/-
Wiring Charge		1	\$120.00	\$120.00	30/-
Tuff Kote		1	\$160.00	\$160.00	40/-
Towing Charge		1	\$80.00	\$80.00	HH
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00	80/-
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00	HH
Remove/Refix Undercarriage (RR)		1	\$400.00	\$400.00	150/-
Re-set Rear ABS System		1	\$400.00	\$400.00	HH
Remove/Refix Fuel Tank		1	\$80.00	\$80.00	HH
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	HH
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System		1	\$200.00	\$200.00	HH
Four Wheel Alignment		1	\$120.00	\$120.00	60/-
Remove/Refix Radiator		1	\$90.00	\$90.00	80/-
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	80/-
Remove/Refix Fuse Box		1	\$120.00	\$120.00	HH
Repair Exhaust Pipe		1	\$80.00	\$80.00	HH
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	150/-
TOTAL LABOUR					
				\$6,760.00	
ESTIMATE TOTAL					
				\$41,811.73	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

09/07/2020 @ 1730hrs
 Not Androm
 Part by Part.
 10 days.
 LKK Auto

Check part prices

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 14-Jul-20

INSURANCE: TII

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA8317J (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
UNIT ASSY, HEADLAMP, LH (LED) <i>mainly broken</i>	1	\$3,455.00	\$3,455.00
CONDENSER ASSY, W/RECEIVER <i>replaced</i>	1	\$1,336.60	\$1,336.60
AIRCON LIQUID HOSE & PIPE <i>1/2"</i>	1	\$580.45	\$580.45
FRONT SUSPENSION LOWER ARM (RH) <i>distorted</i>	1	\$631.90	\$631.90
FRONT SIDE MEMBER REINFORCEMENT PANEL (RH) <i>Damaged</i>	1	\$320.40	\$320.40
FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH) <i>replaced</i>	1	\$330.00	\$330.00
FRONT SIDE MEMBER SIDE COVER (RH) <i>from</i>	1	\$172.55	\$172.55
FRONT LOWER PANEL <i>1/2"</i>	1	\$320.60	\$320.60
GUIDE RADIATOR AIR NO.3 <i>replaced</i>	1	\$229.80	\$229.80
FRONT LOWER SIDE RAIL (RH) <i>1/2"</i>	1	\$230.75	\$230.75
ENGINE UNDER COVER CENTER <i>from</i>	1	\$523.50	\$523.50
ENGINE UNDER COVER FRONT <i>from</i>	1	\$288.30	\$288.30
ENGINE CROSS MEMBER <i>1/2"</i>	1	\$2,504.40	\$2,504.40
FRONT SHOCK ABSORBER (RH) <i>distorted</i>	1	\$398.20	\$398.20
SUB TOTAL			\$11,322.45
LESS 20% <i>25%</i>			\$2,264.49
DISCOUNTED TOTAL			\$9,057.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

14/07/2020

[Signature]

2KK Auto

[Signature]

check part prices.