

PTE LTD

Page : 2 of 2

Sundries (clip / nuts / rivetted cap) ✓	\$500.00	?
Top aircon gas ✓	\$150.00	
Top up radiator coolant ✓	\$180.00	
Labour charge (for 10 days work) ?	\$5,000.00	1500
Spray paint ?	\$3,000.00	900
Claim for loses ?	\$15,000.00	

160 Sin Ming Drive , Sin Ming Autocity
Singapore 575722

10 Days.

part by part.

Refai part phos

Guo Qianf - 82880282

15/7/2020.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

SINGTRADE INVESTMENT PTE LTD

Date : 08/07/20
Ref : ST008/20
Page : 1 of 2

Attn : Officer in charge
Parts for the Porsche Cayenne 2020 Model
Chassis : WP1ZZZ9YZLDA04151

Description	Qty	U/P	Amount
1. Front headlamp <i>✓ CFA</i>	2	\$4,300.00	\$8,600.00
2. Radiator <i>✓ BR</i>	1	\$1,500.00	\$1,500.00
3. Condenser <i>✓ CFA</i>	1	\$2,600.00	\$2,600.00
4. Front Bumper <i>✓ Re</i>	1	\$2,870.00	\$2,870.00
5. Front Bonnet <i>✓ BUC</i>	1	\$4,800.00	\$4,800.00
6. Front Grille <i>✓ Re</i>	1	\$460.00	\$460.00
7. Front Grille 1 <i>?</i>	1	\$412.00	\$412.00
8. Bumper Grille <i>?</i>	2	\$160.00	\$320.00
9. Bumper Grille 2 <i>?</i>	2	\$230.00	\$460.00
10. Bracket <i>?</i>	2	\$120.00	\$240.00
11. Bracket Top <i>?</i>	1	\$250.00	\$250.00
12. Bracket lower <i>?</i>	1	\$237.00	\$237.00
13. Bracket lower 1 <i>?</i>	1	\$170.00	\$170.00
14. Support Bracket <i>?</i>	2	\$200.00	\$400.00
15. Front Grille 2 <i>?</i>	1	\$1,000.00	\$1,000.00
16. Support bracket <i>?</i>	3	\$180.00	\$540.00
17. lower cover <i>?</i>	1	\$200.00	\$200.00
18. Fan cover <i>?</i>	1	\$700.00	\$700.00
19. Fan Assy <i>?</i>	2	\$2,880.00	\$5,760.00
20. Front support panel <i>✓ BR</i>	1	\$1,217.00	\$1,217.00
21. Front support panel 1 <i>?</i>	1	\$85.00	\$85.00
22. Front Reinforcement Bar <i>✓ BT</i>	1	\$1,500.00	\$1,500.00
23. Front Bonnet Hinger <i>✓</i>	2	\$380.00	\$760.00
24. Wire harness <i>?</i>	1	\$800.00	\$800.00
25. Front camera with 360 view control unit <i>?</i>	1	\$4,800.00	\$4,800.00
26. Supplementary items <i>?</i>		\$3,000.00	\$3,000.00
27. Actuating lever <i>✓</i>	1	\$52.00	\$52.00
28. House Lock <i>✓ BT</i>	1	\$200.00	\$200.00