

ASS. REC. BY:

REF: FCZ/ 20007318/ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/W/S/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop n/s Optima

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 70k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SME 5820L Yr Regn: 10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or Wagon

Make: Honda Shuttle c.c. 1496

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 36859 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP7 - 1217438

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 11/7/20 D.O.I. 27/7/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>4/18</u>	<u>3280.32 Confirm</u>

Date/Time, File Pass to? : Prell. Report
1) : Final Report

Date/Time, File Return to? 2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + R.S. \$ _____
Fees: _____
Others: _____
TOTAL: _____

Date: 14.07.2020
 Vehicle No: SME5820L
 Model: HONDA SHUTTLE HYBRID 1.5G
 Chassis: GP71217438-2018
 Reg.Year: 2018

Third Party Insurer: FIRST CAPITAL
 Third Party Veh No: SHA7870J
 Date of Accident: 11.07.2020

NOT NOTION W
4 days *Painting B&P*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>R1</i> \$986.90 ✓
2	REAR TAILGATE "SHUTTLE" EMBLEM	1		<i>M</i> \$46.60 ✓
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>M</i> \$56.20 ✓
4	REAR TAILGATE LOGO EMBLEM	1		<i>M</i> \$48.50 ✓
5	REAR WINDSCREEN RUBBER	1		<i>M</i> \$68.70 ✓
6	REAR TAILGATE INNER TRIM CLIPS	8	\$5.50	<i>M</i> \$44.00 ✗
7	REAR BUMPER	1	<i>Bu & P</i>	\$783.70 ✓
8	REAR BUMPER CLIPS	8	\$5.80	<i>M</i> \$46.40 ✓
9	REAR BUMPER FIXING COVER	1		<i>M</i> \$38.40 ✓
10	REAR END PANEL	1		REPAIR
		SUB TOTAL		\$2,119.40
		LESS 20%		-\$423.88
		PARTS TOTAL		\$1,695.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>M</i> \$60.00 <i>40sn</i>
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>M</i> \$30.00 ✓
3	REAR BUMPER REVERSE SENSOR	1		<i>M</i> \$350.00 <i>20sn</i>
		S/N TOTAL		\$440.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. *500* \$600.00 *400*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC. *600* \$700.00 *600*

LABOUR CHARGES TO REPLACE, REMOVE, REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE. \$150.00 *120*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. \$120.00 *60*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 14.07.2020
Vehicle No: SME5820L
Model: HONDA SHUTTLE HYBRID 1.5G
Chassis: GP71217438-2018
Reg.Year: 2018

Third Party Insurer: FIRST CAPITAL
Third Party Veh No: SHA7870J
Date of Accident: 11.07.2020

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC.
TO EFFECT REPLACE OF REAR BUMPER.

\$100.00 *50/*

LABOUR CHARGES TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.

\$80.00 *20/*

LABOUR TOTAL \$1,750.00

TingAn

TOTAL

\$3,885.52

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	114A
Vehicle Details	
Vehicle No.:	SME5820L
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2020
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5G AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	LEB6561187
Chassis No.:	GP71217438
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,922.00
Original Registration Date:	05 Oct 2018
First Registration Date:	05 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$12,691.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Oct 2028
PARF Rebate Amount:	\$9,518.00
Intended COE Rebate Details	
COE Expiry Date:	04 Oct 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,301.00
COE Rebate Amount:	\$25,726.00
Total Rebate Amount:	\$35,244.00

The information contained herein is correct as at 15 Jul 2020

OK