

Date: 14.07.2020
Vehicle No: SME5820L
Model: HONDA SHUTTLE HYBRID 1.5G
Chassis: GP71217438-2018
Reg.Year: 2018

Third Party Insurer: FIRST CAPITAL
Third Party Veh No: SHA7870J
Date of Accident: 11.07.2020

*NOT Authorised
4 days Melony B & paint*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Re</i> \$986.90 ✓
2	REAR TAILGATE "SHUTTLE" EMBLEM	1		<i>Re</i> \$46.60 ✓
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>Re</i> \$56.20 ✓
4	REAR TAILGATE LOGO EMBLEM	1		<i>Re</i> \$48.50 ✓
5	REAR WINDSCREEN RUBBER	1		<i>Re</i> \$68.70 ✓
6	REAR TAILGATE INNER TRIM CLIPS	8	\$5.50	\$44.00 ✓
7	REAR BUMPER	1	<i>Bu/Re</i>	\$783.70 ✓
8	REAR BUMPER CLIPS	8	\$5.80	<i>Re</i> \$46.40 ✓
9	REAR BUMPER FIXING COVER	1		<i>Re</i> \$38.40 ✓
10	REAR END PANEL	1		REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SUB TOTAL	\$2,119.40
LESS 20%	-\$423.88
PARTS TOTAL	\$1,695.52

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>Re</i> \$60.00 ✓
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>Re</i> \$30.00 ✓
3	REAR BUMPER REVERSE SENSOR	1		<i>Re</i> \$350.00 ✓
S/N TOTAL				\$440.00

LABOUR CHARGES:

- LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. \$600.00 *400*
- LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC. \$700.00 *400*
- LABOUR CHARGES TO REPLACE, REMOVE, REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE. \$150.00 *120*
- LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. \$120.00 *60*

Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch
551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 14.07.2020
Vehicle No: SME5820L
Model: HONDA SHUTTLE HYBRID 1.5G
Chassis: GP71217438-2018
Reg.Year: 2018

Third Party Insurer: FIRST CAPITAL
Third Party Veh No: SHA7870J
Date of Accident: 11.07.2020

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC.
TO EFFECT REPLACE OF REAR BUMPER.

\$100.00 *50/*

LABOUR CHARGES TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.

\$80.00 *20/*

LABOUR TOTAL \$1,750.00

TingAn

TOTAL

\$3,885.52

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

